

# Municipality of Tweed 2022 Budget

#### Index

- 1. Agendas of Budget Meetings
- 2. 2022 Budget Highlights
- 3. Budget Summary and Tax Impacts
- 4. Allocation of Taxes by Department
- 5. Revenue Summary
- 6. Expenditure Summary
- 7. General Government Detailed Budget
- 8. Protection Services Detailed Budget
- 9. Transportation Services Detailed Budget
- 10. Sewer and Water Detailed Budget
- 11. Other Environmental Services Detailed Budget
- 12. Recreation Services Detailed Budget
- 13. Planning Services Detailed Budget
- 14. Capital Budget Summary
- 15. General Government Long Term Capital Plan and Capital Budget
- 16. Protection Services Long Term Capital Plan and Capital Budget
- 17. Transportation Services and Environmental Services Long Term Capital Plan and Capital Budget
- 18. Recreation Services and Planning Services Long Term Capital Plan and Capital Budget
- 19. User Fees By-Law and Water and Sewer Rate By-Laws Review
- 20. Projected 2022 Reserves and Reserve Funds
- 21. Budget Reconciliation, O.Reg. 284/09

# **Municipality of Tweed**

# 2022 Budget Meeting Agenda – Part 1

# November 30, 2021 at 9:00 a.m.

1.	Call to Order	9:00-9:01
2.	Protection Services Long Term Capital Plan and Capital Budget (tab 16)	9:01-9:30
3.	General Governemnt Long Term Capital Plan and Capital Budget (tab 15)	9:30-10:00
3.	Recreation Services and Planning Services Long Term Capital Plan and Capital Budget (tab 18)	10:00-10:45
4.	Transportation Services and Environmental Services Long Term Capital Plan and Capital Budget (tab 17)	10:45-11:30
5.	Capital Budget Summary (tab 14)	11:30-11:45
8.	Adjournment	11:45

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-110-58012	Washroom improvements	17,000.00				17,000.00				-	Convert public washroom at Council Chambers area into accessible washroom
01-110-58014	Annual Computer Renewals	5,360.00				5,000.00				360.00	Annual needs based on long term capital plan
01-110-58014	Annual Printer Renewals	1,130.00				550,63				579.37	Annual needs based on long term capital plan
01-110-58014	Council iPad Renewals	6,000.00				5,000.00				1,000.00	Replacement with each election
01-110-58024	Unfunded 2021 Roof Project	9,527.67				9,527.67				•	Due to rising costs, Council approved funding remainder in 2022 for this
01-110-58025	Building Repairs	30,000.00				30,000.00				-	project 2021 carry over project for administration renovations
01-110-58025	Emergency Exit Improvements	15,000.00				15,000.00				•	Some of the emergency exits for the administration office do not have the panic bars or steps that do not meet code. Propose installing panic bars on 3 doors and improve steps outside 1 door on south side of building that is currently too high of a drop
01-110-58025	Heating repairs									-	Heating duct work in the administration building needs replacement as it is not to code; in addition, there are 3 different heating sources that are conflicting with each other consideration to convert to a single heat source
01-110-58026	Annual Office Furniture Renewals	1,800.00				1,800.00				-	Annual needs based on long term capital plan
	Electronic sign Coming Events sign CAPITAL Non-Budget Items	15,000.00 4,500.00 10,000.00				•				15,000.00 4,500.00 10,000.00	
	•	115,317.67		-	·	83,878.30	-	<u> </u>		31,439.37	- •
01-210-58000	Roof replacement	45,000.00				45,000.00				-	Roof was partially repaired with addition this year, the remainder of the roof is required to be completed. Costs based on verbal estimate from local contractor. To be funded with remainder of the fire hall reserve from 2021 plus municipal building reserve for the remainder of costs

Obligatory

Account 01-210-58011	Capital Project Unfunded 2021 Firehall Addition Project	2022 Budgeted Expense 4,892.14	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact 4,892.14	Notes Due to rising costs, Council approved funding remainder in 2022 for this project
01-210-58132 01-210-58132	Rescue Equipment Vehicle Replacement	60,000.00				60,000.00				-	Costs based on verbal estimate from local dealer for a 1 ton truck to replace the 2010 Dodge Crew Cab
		109,892.14				105,000.00		•		4,892.14	•
01-310-58131	Vanderwater Road	652,860.00						652,860.00		•	Hwy 37 to Ervine Rd 30 mm Hotmix Everlife
01-310-58131	Queensborough Road	240,000.00		132,398.00				107,140.00		464.00	Barry Rd to Boundary, Hall parking lot with asphalt, gutter, catch basis, 50 mm
01-310-58131	King Street	25,000.00								25,000.00	HL3 Hotmix Queensborough 30mm Everlife Hotmix
01-310-58131	Charles Rd stormwater management	15,000.00								15,000.00	Stage 1 of Jewell Engineering Proposal
01-310-58131	Sidewalk	8,000.00								8,000.00	50 metres on St. Joseph St where low and holding
01-310-58131	Victoria Cemetery fencing	17,808.00								17,808.00	water/ice 750' of 4' chain link, 9 gauge mesh, residential frame with single vehicle gate and double vehicle
01-310-58132	Tandem Plow/Wing combination	280,000.00				280,000.00				-	gate Like to purchase new with rent to own option as backhoe needs \$20,000 work on engine
	Backhoe Mower for Holland Tractor Patrol Truck (replace 300)	170,000.00 48,000.00 55,000.00				118,656.34				51,343.66 48,000.00 55,000.00	
	Greatrix Bridge Pre-engineering Joe Allore Bridge	326,025.00 108,500.00				48,696.00 108,500.00				277,329.00	
00.10-00100	Tro-chigh centring over more brings	1,946,193.00	· ·	132,396.00	· .	555,852.34	•	760,000.00		497,944.66	•
01-330-58014	GRAVEL PIT Esker Rd Pit Licence	13,590.00				1	13,590.00			<u>.</u>	
		13,590.00			•		13,590.00	•			•
01-410-58022	SANITARY SEWER OCWA	16,667.00				18,667.00					•
		16,667.00				16,667.00				<u> </u>	•
	River Crossing	1,029,682.51	404,800.00	337,333.33		287,549.18				•	Green Stream 2 grant application
01-420-58001	Water Tower Interior Coating Water filter media system WATER Water Meters & Hydrants & V	45,000.00 30,000.00				45,000.00 30,000.00				- -	2 hydrants and shut off valves
01-420-58022	WATER OCWA	25,726,00 1,130,408,51	404,800.00	337,333.33		25,726.00 388,275,18	•				
	BluMetric Hunt Road BluMetric Marlbank Road	22,400.00 5,700.00	***************************************				22,400.00 5,700.00				•
		28,100.00	•	•	•	•	28,100.00			•	•
01-510-58000	Recreation Area Shelter	40,000.00				40,000.00				·	

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax	t Note
01-510-58000		2,500.00				•	•	•		2,500.00	
01-510-58000	· · - <b>F U</b>	40,000.00				37,340.50				2,659.50	
01-510-58018		15,000.00								15,000.00	
01-510-58019		5,000.00								5,000.00	
01-510-58038		1,000.00								1,000.00	
01-510-58039		10,000.00				5,000.00				5,000.00	
01-510-58050		45,000.00				•				45,000.00	
01-510-58050		10,000.00								10,000.00	
01-510-58050		250,000.00			200,000.00			43,154.19		6,845.81	
01-510-58050		5,000.00								5,000.00	
01-510-58050	Beach sand	25,000.00								25,000.00	
01-510-58132	New mower	15,000.00								15,000.00	
01-510-58132	Rake for tractor	1,000.00								1,000.00	
01-510-58132	Aqua thruster (2)	20,000.00								20,000.00	
	. ,,	484,500,00	•		200,000.00	82,340.50		43,154.19		159,005.31	=
01-512-58014	HAMLET REC Actinolite Hall Improver	3,000.00								3,000.00	,
01-514-58014										3,000.00	
	HAMLET REC Queensborough Hall In	-,								3,000.00	
01-516-58020		357,000.00			256,400.00					100,600.00	
01-518-58014					200,400.00					3,000.00	
01-010-00014	Trance Neo Monassay Hair Impre	369,000.00			256,400.00	-				112,600.00	_
						05 000 00					
01-520-58000		25,000.00			05 000 00	25,000.00				-	
01-520-58000		102,000.00			85,000.00	17,000.00				-	
01-520-58132		45,000.00				45,000.00 6,000.00				•	
01-520-58132		6,000.00				623.00				2,377.00	
01-520-58132		3,000.00				623.00				1,500.00	
01-520-58132		1,500.00								1,650.00	
01-520-58132		1,650.00				6,000.00				1,000.00	
01-520-58132		6,000.00				4,000.00				•	
01-520-58132	Floor scrubber	4,000,00			85,000.00	103.623.00				5,527.00	_
		<u>194,150.00</u>			00,000,00	103,623.00			·	0,027.00	=
01-525-58000		3,000.00								3,000.00	
01-525-58000	Splashpad rain diverter	20,000.00				1,250.00				18,750.00	
01-525-58000	Splashpad replace painting instead of	500.00								500.00	
		23,500.00	•	•	•	1,250.00			-	22,250.00	_
01-555-58000	Pool liner	200.000.00				89,000.00				111,000.00	J
01-555-58052		25,000.00				25,000.00				25,000.00	
01-000-00002	Gas fieater to poor	225,000.00				89,000.00				136,000.00	
										4 000 00	
01-125-58017		4,000.00								4,000.00 6,000.00	
01-125-58132	Banners	6,000.00						<del>-</del>		10,000.00	
		10,000.00		·····		•		<del></del>		10,000,00	-
		4,666,318.32	404,800.00	469,729.33	541,400.00	1,425,886.32	41,690.00	803,154.19		979,658.48	<u>.</u>

## Municipality of Tweed Long Term Capital Plan - Administration

Asset	Year Acquired/ Last Updated	Expected Replacement/ Renovation	Historical Cost	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031
Elevator	2017	2042	40,000.00										
Hungerford Office	2018		82,802.12										
(Lions)			•										
Furnace (rooftop units)	2014	2034	83,486.22										
Administration building	2011	2051	300,850.98	62,000.00									
Admin ramp/railings	2015	2055	18,545.00										
Elzevir Office	1990	2030	118,036.80									118,036.80	
Admin Bldg Signage	2012	2032	5,762.67		•								
Library - HVAC system	2020		66,601.90										
Parking Lot pavement	2016		17,362.32										
Electronic sign	2021	2022	14,093.34	19,500.00									
Computers		every 5 years	32,209.10	5,360.00	5,360.00	5,360.00	5,360.00	5,360.00				4 000 00	4 000 00
Furniture		Every 15 years	27,224.89	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00
Debit Machine	2007	Not to be renewed	2,500.00										
Fax Machine	2012	2027	594.30						594.30				
Filing Cabinets	2012	Not to be renewed	7,151.08										
Kitchen Fridge	2008	2023	600.00		600.00								
Map Cabinet	2007	Not to be renewed	1,600.00										
Kitchen Microwave	1989	2026	200.00					200.00					
Phone system	2021	2041	7,341.98										
Printers	2020	every 5 years	5,657.51	1,130.00	1,130.00	1,130.00	1,130.00	1,130.00					
iPads	2012	every 4 years	5,837.74	6,000.00				6,000.00					
Solar Panel - Country Garage	2013	2033	40,610.38										
Total Costs		-	839,068.33	95,790.00	8,890.00	8,290.00	8,290.00	14,490.00	2,394.30	1.800.00	1,800.00	119,836.80	1,800.00
Administration Capital Reserve			22,700.00	12,350.63	2,783.34	1,937.50	1,870.00	3,558.53	200.00	•		·	·
Municipal Building Reserve			267,114.40	62,000.00								118,036.80	
Remaining Amounts to be Funded				21,439.37	6,106.66	6,352.50	6,420.00	10,931.47	2,194.30	1,800.00	1,800.00	1,800.00	1,800.00
2022 Transfer to Reserves Requirement		[	36,460.53	] -	3,053.33	2,117.50	1,605.00	2,186.29	365.72	257.14	225.00	200.00	180.00
5 Year basis only - Admin 5 Year basis only - building			9,327.84										

# Municipality of Tweed Long Term Capital Plan - Administration

Asset	2032	2033	2034	2035	2036	2040	2041	2042	2051	2055	2058
Elevator Hungerford Office (Lions) Furnace (rooftop units) Administration building Admin ramp/railings			83,486.22			60,000.00		40,000.00	300,850.98	18,545.00	82,802.12
Elzevir Office Admin Bldg Signage Library - HVAC system Parking Lot pavement Electronic sign Computers	5,762.67			66,601.90	17,362.32						
Furniture Debit Machine	1,800.00	1,800.00	1,800.00	1,800.00	1,800.00						
Fax Machine Filing Cabinets											
Kitchen Fridge Map Cabinet											
Kitchen Microwave Phone system Printers iPads							7,341.98				
Solar Panel - Country Garage		40,610.38									
Total Costs Administration Capital Reserve	7,562.67	42,410.38	85,286.22	68,401.90	19,162.32	60,000.00	7,341.98	40,000.00	300,850.98	18,545.00	82,802.12
Municipal Building Reserve			83,486.22	3,591.38							
Remaining Amounts to be Funded	7,562.67	42,410.38	1,800.00	64,810.52	19,162.32	60,000.00	7,341.98	40,000.00	300,850.98	18,545.00	82,802.12
2022 Transfer to Reserves Requirement 5 Year basis only - Admin 5 Year basis only - building	687.52	3,534.20	138.46	4,629.32	1,277.49	3,157.89	367.10	1,904.76	10,028.37	545.44	2,237.90

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-110-58012	Washroom improvements	17,000.00				17,000.00				-	Convert public washroom at Council Chambers area into accessible washroom
01-110-58014	Annual Computer Renewals	5,360.00				5,000.00				360.00	Annual needs based on long term capital plan
01-110-58014	Annual Printer Renewals	1,130.00				550.63				579.37	Annual needs based on long term capital plan
01-110-58014	Council iPad Renewals	6,000.00				5,000.00				1,000.00	Replacement with each election
01-110-58024	Unfunded 2021 Roof Project	9,527.67				9,527.67					Due to rising costs, Council approved funding remainder in 2022 for this
01-110-58025	Building Repairs	30,000.00				30,000.00					project 2021 carry over project for administration renovations
01-110-58025	Emergency Exit Improvements	15,000.00				15,000.00					Some of the emergency exits for the administration office do not have the panic bars or steps that do not meet code. Propose installing panic bars on 3 doors and improve steps outside 1 door on south side of building that is currently too high of a drop
	Heating repairs  Annual Office Furniture Renewals	1 800 00				1,800.00					Heating duct work in the administration building needs replacement as it is not to code; in addition, there are 3 different heating sources that are conflicting with each other-consideration to convert to a sincle heat source Annual needs based on
		1,800.00				1,800.00				45 000 00	long term capital plan
01-110-58132 01-110-58132 01-110-58100	Electronic sign Coming Events sign CAPITAL Non-Budget Items	15,000.00 4,500.00 10,000.00								15,000.00 4,500.00 10,000.00	Set amount for potential unknown capital items. In 2021 it funded the required phone system upgrades.
		115,317.67	-	-	-	83,878.30	-	-	-	31,439.37	-

# Municipality of Tweed Long Term Capital Plan - Fire Department

Driveway   2019   2023   2,000.00   2,000.	Asset	Year Acquired / Last Updated	Expected Replacement/ Renovation	Historical Cost/Estimated Replacement	2022	2023	2024	2025	2026	2027	2029
Firehall Case Funece 2017 2037 22,000.00 Mobile Generators 2005 2030 72,345.00				•						2,000.00	2,000.00
Fire Hall Gas Furnace Mobile Generators 2005 2037 22,000.00 Mobile Generators 2006 2030 72,345.00 5	•			•	45 000 00	2,000.00				•	•
Mobile Generators   2008   2030   72,345.00				•	40,000.00			,			
Extraction Tool				•							
Portable Pump											8,500.00
Mater Pump   2012   2023   8,500.00   8,500.00   8,500.00									8,500.00		
Mater Pump	•								18,000.00		
Airpack bottles/masks 2019 2034 5,800.00   102,000.00   1						8,500.00					
Air Pacs 2012 2027 102,000.00				•		•					
Air Pacs 2017 2032 41,000.00   Air Pacs 2020 2035 20,171.15   Air compressor 2015 2030 42,500.00   Radios/pagers 2015 2030 42,500.00   Radios/pagers 2015 2030 42,500.00   Repeater Tower 2021 2036 20,000.00   Offroad Vehicle 2020 2035 22,500.00   Rescue Equipment 2006 2023 45,000.00   Rescue Equipment 2014 2024 8,000.00   2015 Tanker Truck 2018 2038 310,000.00   2010 Dodge Crew Cab 2017 2022 60,000.00   Binternational Pumper 2007 2027 600,000.00   ATV Trailer 2020 2035 5,000.00   ATV Trailer 2020 2035 5,000.00   AIr bags 2021 2036 2051 5,000.00   Air bags 2021 2036 2051 5,000.00   AIr Bags 2021 2036 2,512,953.28 105,000.00   AIr Building Reserve Used   Current Fire Equipment Reserve Used   Current Fire Equip	•									102,000.00	
Air Pacs 2020 2035 20,171.15 Air Compressor 2015 2030 42,500.00 18,000.00 18,000.00 Radios/pagers 2015 2023 18,000.00 18,000.00 Repeater Tower 2021 2036 20,000.00 Grass Fire Skid Unit 2019 2034 17,000.00 Coffroad Vehicle 2020 2035 22,500.00 Rescue Equipment 2006 2023 45,000.00 45,000.00 Roscue Equipment 2006 2023 45,000.00 60,000.00 Roscue Equipment 2014 2024 8,000.00 60,000.00 Roscue Camera 2014 2024 8,000.00 60,000.00 Roscue Camera 2014 2024 8,000.00 60,000.00 Roscue Value											
Air compressor Radios/pagers 2015 2023 42,500.00 Radios/pagers 2015 2023 18,000.00 18,000.00 Radios/pagers 2015 2023 20,000.00 Repeater Tower 2021 2036 20,000.00 Grass Fire Skid Unit 2019 2034 17,000.00 Offroad Vehicle 2020 2035 22,500.00 Rescue Equipment 2006 2023 45,000.00 Rescue Equipment 2006 2023 45,000.00 Rescue Equipment 2014 2024 8,000.00 Rescue Equipment 2014 2024 8,000.00 Rescue Equipment 2017 2022 60,000.00 Rescue Equipment 2017 2022 60,000.00 Rescue Van 2010 2030 300,000.00 Rescue Van 2010 2030 300,000.00 Rescue Van 2010 2030 300,000.00 Rescue Van 2010 2030 5,000.00 Rescue Van 2010 2030 5,000.00 Rescue Van 2010 2030 300,000.00 Rescue Van 2010 2030 5,000.00 Rescue Van 2010 2030 70,000.00 Rescue Van 2010 2030 Rescue Van 2010 2030 Rescue Van 2010 2030 Rescue Van 2010 Rescue Va											
Radios/pagers 2015 2023 18,000.00 18,000.00   18,000.00   Repeater Tower 2021 2036 20,000.00   Grass Fire Skid Unit 2019 2024 8,000.00   45,000.00   Rescue Equipment 2006 2023 45,000.00   45,000.00   Rescue Equipment 2006 2023 45,000.00   Rescue Equipment 2006 2024 8,000.00   Rescue Equipment 2006 2024 8,000.00   Rescue Equipment 2006 2024 8,000.00   Rescue Equipment 2011 2022 60,000.00   Grass Fire Truck 2018 2038 310,000.00   Grass Fire Trailer 2010 2030 300,000.00   Rescue Van 2010 2030 5,000.00   Rescue Van 2010 2030 5,000.00   Rescue Van 2010 2030 5,000.00   Rescriber Trailer 2010 2030 9,000.00   Reserve Used   Remaining Amounts to be Funded 2022 Transfer to Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserve Requirement 5 year basis only - building 5 year basis only - building 5 year basis only - 111,500.00   111,50											
Repeater Tower   2021   2036   20,000.00   Care	•					18,000.00					
Grass Fire Skid Unit 2019 2034 17,000.00 Officed Vehicle 2020 2035 22,500.00 Rescue Equipment 2006 2023 45,000.00   45,000.00   8,000.00   10,500.00   10,500.00   10,500.00   10,500.00   10,500.00   11,833.33   1,312.50   11,833.33   1,312.50   11,833.33   1,312.50   11,833.33   1,312.50   11,833.33   1,312.50   11,500.00   1,50											
Offroad Vehicle 2020 2035 22,500.00 Rescue Equipment 2006 2023 45,000.00   45,000.00   8,000.00   2015 Tanker Truck 2018 2038 310,000.00   2010 Dodge Crew Cab 2017 2022 60,000.00   60,000.00   2010 Dodge Crew Cab 2017 2022 60,000.00   60,000.00   2010 Dodge Crew Cab 2016 2036 385,000.00   2010 Rescue Van 2010 2030 300,000.00   2010 2030 300,000.00   2010 2030   2010 2030   2010 2035   5,000.00   2010 2030   201	•	2019	2034	17,000.00							
Rescue Equpiment   2006   2023   45,000.00   45,000.00   8,000.00   8,000.00   8,000.00   10,500.00   10,500.00   10,500.00   11,833.33   1,312.50   11,833.33   1,312.50   11,833.33   1,312.50   1,500.00   1,5	• • • • • • • • • • • • • • • • • • • •			•							
Infrared Camera 2014 2024 8,000.00 8,000.00 2015 Tanker Truck 2018 2038 310,000.00 60,	Rescue Equpiment	2006	2023	45,000.00		45,000.00			-		
2010 Dodge Crew Cab		2014	2024	8,000.00			8,000.00				
06 International Pumper 2007 2027 600,000.00	2015 Tanker Truck	2018	2038	310,000.00							
06 International Pumper 2007 2027 600,000.00	2010 Dodge Crew Cab	2017	2022	60,000.00	60,000.00						
Tanker Truck Rescue Van 2010 2030 300,000.00 ATV Trailer 2020 2035 5,000.00 Grass Fire Trailer 2010 2030 5,000.00 Air bags 2021 2036 2036 5,000.00  Total Costs Current Fire Building Reserve Used Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Syear basis only -  5 year basis only -  2016 2030 300,000.00 300,000.00 5,000.00 2030 5,000.00 73,500.00 8,000.00 42,000.00 42,000.00 42,000.00 26,500.00 704,000.00 10,500.00 60,000.00 71,500.00 8,000.00 - 42,000.00 - 42,000.00 - 42,000.00 - 671,000.00 10,500.00 - 111,833.33 1,312.50		2007	2027	600,000.00						600,000.00	
ATV Trailer 2020 2035 5,000.00 Grass Fire Trailer 2010 2030 5,000.00 Air bags 2021 2036 9,000.00 Total Costs Current Fire Building Reserve Used Current Fire Equipment Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00 Sp. 000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 5,000.00 704,000.00 10,500.00 10,500.00 23,202.02 5	•	2016	2036	385,000.00							
Grass Fire Trailer 2010 2030 5,000.00 Air bags 2021 2036 2036 9,000.00 Total Costs 2,512,953.28 105,000.00 73,500.00 8,000.00 42,000.00 26,500.00 704,000.00 10,500.00 23,202.02 Reserve Used Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00	Rescue Van	2010	2030	300,000.00							
Air bags 2021 2036 9,000.00  Total Costs 2,512,953.28 105,000.00 73,500.00 8,000.00 42,000.00 26,500.00 704,000.00 10,500.00  Current Fire Building 23,202.02  Reserve Used Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00	ATV Trailer	2020	2035	5,000.00							
Total Costs	Grass Fire Trailer	2010									
Current Fire Building Reserve Used Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only -  111,500.00  23,202.02  60,000.00 71,500.00 8,000.00 - 26,500.00 33,000.00 - 26,5	Air bags	2021	2036								
Reserve Used Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only -  111,500.00  60,000.00 71,500.00 8,000.00 - 42,000.00 - 42,000.00 - 42,000.00 - 671,000.00 - 671,000.00 - 10,500.00 - 111,833.33 - 1,312.50 - 111,500.00	Total Costs			2,512,953.28		73,500.00	8,000.00	42,000.00	26,500.00	704,000.00	10,500.00
Current Fire Equipment Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only -  111,500.00  60,000.00 71,500.00 8,000.00 - 42,000.00 - 42,000.00 - 671,000.00 - 671,000.00 - 10,500.00 - 111,833.33 - 1,312.50 - 111,500.00	Current Fire Building				23,202.02						
Reserve Used Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00  21,797.98 2,000.00 - 42,000.00 - 671,000.00 10,500.00  - 111,833.33 1,312.50  111,500.00											
Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00	Current Fire Equipment				60,000.00	71,500.00	8,000.00	-	26,500.00	33,000.00	
be Funded 2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00  111,500.00  111,500.00  111,500.00	Reserve Used		•								40.500.00
2022 Transfer to Reserves Requirement 5 year basis only - building 5 year basis only - 111,500.00  111,500.00  10,500.00 - 10,500.00 - 111,833.33 1,312.50	Remaining Amounts to				21,797.98	2,000.00	-	42,000.00	-	671,000.00	10,500.00
Reserves Requirement 5 year basis only - building 5 year basis only - 11,833.33 11,500.00	be Funded				•					444 000 00	4 040 50
5 year basis only - 11,833.33 building 5 year basis only - 111,500.00				306,539.14	-	1,000.00	-	10,500.00	-	111,833.33	1,312.50
building 5 year basis only - 111,500.00	· · · · · · · · · · · · · · · · · · ·										
5 year basis only - 111,500.00				11,833.33							
- 1	building										
equinment	5 year basis only -			111,500.00							
equipment	equipment										

# Municipality of Tweed Long Term Capital Plan - Fire Department

Asset	2030	2031	2032	2034	2035	2036	2037	2038	2040
Driveway Firehall and renovations Fire Hall Gas Furnace Mobile Generators Extraction Tool Portable Pump	72,345.00	2,000.00					22,000.00		1,500,000.00
Jaws of Life Water Pump Airpack bottles/masks Air Pacs				5,800.00					
Air Pacs Air Pacs Air compressor	42,500.00		41,000.00		20,171.15				
Radios/pagers Repeater Tower Grass Fire Skid Unit Offroad Vehicle				17,000.00	22,500.00	20,000.00			
Rescue Equpiment Infrared Camera 2015 Tanker Truck 2010 Dodge Crew Cab								310,000.00	
06 International Pumper Tanker Truck Rescue Van ATV Trailer	300,000.00				5,000.00	385,000.00			
Grass Fire Trailer Air bags	5,000.00					9,000.00			
Total Costs Current Fire Building Reserve Used Current Fire Equipment Reserve Used	419,845.00	2,000.00	41,000.00	22,800.00	47,671.15	414,000.00	22,000.00	310,000.00	1,500,000.00
Remaining Amounts to be Funded 2022 Transfer to Reserves Requirement	419,845.00 46,649.44	2,000.00	41,000.00 3,727.27	22,800.00 1,753.85	47,671.15 3,405.08	414,000.00 27,600.00	22,000.00 1,375.00	310,000.00 18,235.29	1,500,000.00 78,947.37
5 year basis only - building 5 year basis only - equipment									

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-210-58000	Roof replacement	45,000.00				45,000.00					Roof was partially repaired with addition this year, the remainder of the roof is required to be completed. Costs based on verbal estimate from local contractor. To be funded with remainder of the fire hall reserve from 2021 plus municipal building reserve for the remainder of costs
01-210-58011	Unfunded 2021 Firehall Addition Projeton Vehicle Replacement	60,000.00				60,000.00				4,892.14 -	Due to rising costs, Council approved funding remainder in 2022 for this project Costs based on verbal estimate from local dealer for a 1 ton truck to replace the 2010 Dodge Crew Cab
		109,892.14	-	•		105,000.00	-	-	-	4,892.14	•

Asset	Year Acquired / Last Updated	Replacement/	Replacement Cost Estimates	2022	2023	2024	2025	2026	2027	2028
Per Asset Management Plan -	_									
Priorities	7.0									
Lost Channel Bridge (6) -										
Lost Channel Rd										
Catons Bridge N (8) - Carss										
Rd										
Catons Bridge S (7) - Carss										
Rd										
East Red Bridge (30) - Black							-			
River Rd							× .			
West Red Bridge (31) - Black River Rd							-			
Morton Memorial Bridge (19)										
Ross Bridge (40)										
Joe Trudeau Bridge (49)										
Moira River N Connection		2022	1,029,682.51	1,029,682.51						
(Bridge St E to Moira St)		1000000	,,,							
Hydrant 70		2022	15,000.00	15,000.00						
Queensborough Rd (Barry		2022	240,000.00	240,000.00						
Road to Boundary and Hall										
Parking Lot) & Stormwater										
Charles Rd (Charles Court to		2023	120,000.00		120,000.00					
end)			504500		5.045.00					
Pomeroy Court (College to		2023	5,915.00		5,915.00					
end)		2022	27 400 00		37,400.00					
Pomeroy Court (College to end) - Water		2023	37,400.00		37,400.00					
Pomeroy Court (College to		2023	24,000.00		24,000.00					
end) - Sewer		2020	24,000.00		21,000.00					
Rocky Alter Bridge (12) -		2024	855,000.00			855,000.00				
Allore Rd										
Arthur (Brooklyn to Louisa)		2024	61,456.00			61,456.00				
Arthur (Brooklyn to Louisa) -		2024	224,400.00			224,400.00				
Water										
Arthur (Brooklyn to Louisa) -		2024	131,500.00			131,500.00				
Sewer		22220				00 000 00				
Arthur - Hydrant 84, 83 and 82		2024	30,000.00			30,000.00	510 000 00			
Reynolds Culvert (38) - Flinton		2025	510,000.00				510,000.00			
Road Hungerford (Park to Metcalf)		2025	65,260.00				65,260.00			
Hungerford (Park to Metcalf) -		2025					246,992.00			
Water		2025	240,332.00				210,002.00			
Hungerford (Park to Metcalf) -		2025	148,500.00				148,500.00			
gonora (r unit to Motodii)		2020	0,000.00							

Sewer

	Year Acquired / Last	Expected Replacement/	Replacement							
Asset	Updated		Cost Estimates	2022	2023	2024	2025	2026	2027	2028
Hydrant 94 and 93	Opuatou	2025	20,000.00				20,000.00			
Quinns Lane (Victoria St to		2025	13,943.00				13,943.00			
Colborne)										
Sexsmith (Hwy 7 to end)		2025	37,950.00				37,950.00			
James St S (River E to		2026	35,000.00					35,000.00		
George)			200 - 000 - 400 1120 000 000 000 000 000 000 000 000							
James St S (River E to		2026	62,900.00					62,900.00		
George) - Water										
James St S (River E to		2026	64,000.00					64,000.00		
George) - Sewer										
Jamieson E (Victoria N to		2026	79,831.00					79,831.00		
James N)			222 224 22					205 550 00		
Jamieson E (Victoria N to		2026	325,550.00					325,550.00		
James N) - Water		2222	100 500 00					192,500.00		
Jamieson E (Victoria N to		2026	192,500.00					192,500.00		
James N) - Sewer		2026	10,000.00					10,000.00		
Jamieson E - Hydrant 64 Hannah (Louisa to James N)		2026	17,428.00					17,428.00		
Hannah (Louisa to James N) -		2026	78,200.00					78,200.00		
Water		2020	70,200.00					3.54		
Hannah (Louisa to James N) -		2026	46,000.00					46,000.00		
Sewer			,							
James St N (Jamieson to		2026	20,271.00					20,271.00		
Hannah)										
James St N (Jamieson to		2026	95,200.00					95,200.00		
Hannah) - Water										
James St N (Jamieson to		2026	52,500.00					52,500.00		
Hannah) - Sewer									100 500 00	
Moira (Brooklyn to Hwy 37)		2027	133,528.00						133,528.00	
Moira (Brooklyn to Hwy 37) -		2027	441,150.00						441,150.00	
Water		2007	205 500 00						265,500.00	
Moira (Arthur to Hwy 37) - Sewer		2027	265,500.00						205,500.00	
Moira - Hydrant 43		2027	10,000.00						10,000.00	
Mona - Hydrant 45		2021	10,000.00							
All Other Assets										
Hydrants (1)				15,000.00						
Vanderwater Rd (Hwy 37 to		2022	652,860.00	652,860.00						
Ervine Road)										
King St (Queensborough)		2022	25,000.00	25,000.00						
Charles Rd Stormwater		2022		15,000.00						
Management										
Greatrix Bridge - Robinson Rd		2022		326,025.00	4 500 000 00					
Joe Allore Bridge (#46)		2023		108,500.00	1,590,000.00					
McClellan St		2023	900,000.00		900,000.00					

	Year Acquired	Expected								
	/ Last	Replacement/	Replacement							
Asset	Updated	Renovation	<b>Cost Estimates</b>	2022	2023	2024	2025	2026	2027	2028
McClellan St - Water		2023	300,000.00		300,000.00					
McClellan St - Sewer		2023	300,000.00		300,000.00					
Dowling Bridge		2024	585,000.00			585,000.00				11,096,840.00
Roads - all others noted in										11,050,040.00
AMP										2,151,000.00
Bridges - all others noted in AMP										2,101,000.00
Water - all others noted in										4,035,299.00
AMP										, ,
Sewer - all others noted in										1,621,563.00
AMP								1		
Stormwater - all others noted										
in AMP										
Per TCA (other assets not yet	i									
in AMP)			400 000 00		400 000 00					
2 Ton	0040	2023	100,000.00		100,000.00					
Stoco Garage Stoco Sand Dome	2010 2016	2050 2036	102,453.83 98,701.86							
Marlbank Sand Dome	2016	2046	106,106.00							
Countryman Garage	1978	2040	79,948.80							
Countryman Salt Dome	1978	2025	38,569.05				38,569.05			
Actinolite Garage	1992	2032	181,301.75							
Actinolite Sand Dome	1992	2032	103,390.00							
Quanset Hut	1975	2030	25,458.02							
PW Dome	2010	2050	53,628.80							
2006 Case/580 Backhoe	2006	2022	170,000.00	170,000.00						
2008 550 Ford Dump	2008	2025	280,000.00				280,000.00			
Truck/Plow		****		000 000 00						
New Dump truck/plow		2022	•	280,000.00			300,000.00			
2008 Sterling Lt9513 Tandem	2008	2025	300,000.00 55,000.00	EE 000 00			300,000.00			
2008 F250 Pickup 2011 Intern 7600 Tandem	2008 2011	2022 2023	300,000.00	55,000.00	300,000.00					
2011 Excavator	2011	2023	227,120.54		227,120.54					
2012 Intern 7600 Tandem	2011	2024	300,000.00		227,120.04	300,000.00				
1997 Holland Tractor	1997	2030	15,264.00	48,000.00		000,000.00				
2020 Ford F150	2020	2030	29,500.00							
2013 John Deere Loader	2013	2023			175,102.50					
2016 Ford 1/2 Ton	2016	2026	•					37,019.93		
2015 Mack Tandem	2015	2025	242,847.79				242,847.79			
2015 Mack Truck	2016	2026	•					229,669.00		005 000 50
2017 Mack Tandem Plow &	2018	2028	265,663.59							265,663.59
Wing		**	70 100 17							70,486.15
1996 Volvo/L-70 Loader	2013	2028	•							/U <sub>1</sub> 400.15
2002 Volve/G740 Grader	2018	2033	213,074.20							

Asset	Year Acquired / Last Updated	Expected Replacement/ Renovation	Replacement Cost Estimates	2022	2023	2024	2025	2026	2027	2028
2014 1/2 Ton Truck	2018			2022	2023	2024	2020	2020		17,119.00
Gravel Packer	2019		•							11,110.00
GPS Indicators	2015						19,524.38			
Sidewalk Plow blower &	2016						,	67,451.50		
broom	20.0	2020	.,					·		
Sweeper Brush	2013	2023	1,765.54		1,765.54					
Grader	2019	2039	380,993.33		,					
Stoco Shop Furnace	2019	2039	40,308.15							
Culvert Steamer	2021	2061	17,512.90							
Culvert Steamer	1990									
Hunt Rd Well - WDS	2013		•							
Maribank Rd Well WDS	2013									
Weigh scales	2013				43,536.80					
WDS Compactor 936 Cat	2008				93,628.85					
WDS Scale Bldg	2013									
WDS Depot	2008									
2007 JD 605C Crawler Loader	2021	2037	97,587.84							
Total Costs			13,715,218.90	2,980,067.51	4,218,469.23	2,187,356.00	1,923,586.22	1,413,520.43	850,178.00	19,257,970.74
Can Tay Funding				760 000 00	400.041.00	400,041.00	400,041.00	400,041.00	400.041.00	400,041.00
Gas Tax Funding				760,000.00		132,396.00	132,396.00	132,396.00	132,396.00	132,396.00
OCIF Funding				132,396.00	132,396.00	132,390.00	132,350.00	132,350.00	132,330.00	102,000.00
Other Grants Current Waste Reserve Fund			1,268,947.07	742,133.33	137,165.65					
Used			1,200,947.07		137,100.00					
Current Road Reserve Used			398,656.34	398,656.34						
Current Bridge Reserve Used			244,514.71	157,196.00	87,318.71					
Current Water Reserve			653,190.00	317,549.18	337,400.00	- 1,759.18				
Current Sewer Reserve			616,231.06	517,545.10	324,000.00	131,500.00	148,500.00	12,231.06		
Remaining Amounts to be			010,201.00	472,136.66	2,800,147.87	1,525,178.18	1,242,649.22	868,852.37	317,741.00	18,725,533.74
Funded				2,.00.00	2,000,	.,020,	.,,		•	,
2022 Transfer to Reserves			6,367,965.15	_	1,400,073.94	508,392.73	310,662.31	173,770.47	52,956.83	2,675,076.25
Requirement										
•										
	5 year	Water	190,094.73							
	-	Sewer	262,405.12							
		Roads	912,005.03							
		Bridges	1,081,351.40							
		Waste	-							

Asset	2029	2030	2031	2032	2033	2035	2036	2037	2038	2039	2040
McClellan St - Water McClellan St - Sewer											
Dowling Bridge Roads - all others noted in AMP	1,559,268.00	1,683,296.00	1,150,479.00	989,568.00	2,333,175.00		834,000.00				
Bridges - all others noted in AMP	3,232,500.00										
Water - all others noted in AMP	627,200.00	395,250.00	40,000.00	20,000.00	10,000.00		100,000.00	10,000.00	217,650.00	60,000.00	
Sewer - all others noted in AMP	296,253.00	233,500.00				60,000.00			123,552.00	60,000.00	20,000.00
Stormwater - all others noted in AMP											
Per TCA (other assets not yet in AMP)											
2 Ton Stoco Garage Stoco Sand Dome							98,701.86				
Maribank Sand Dome Countryman Garage							90,701.00				79,948.80
Countryman Salt Dome Actinolite Garage				181,301.75							
Actinolite Sand Dome		05 450 00		103,390.00							
Quanset Hut PW Dome		25,458.02									
2006 Case/580 Backhoe 2008 550 Ford Dump											
Truck/Plow New Dump truck/plow											
2008 Sterling Lt9513 Tandem 2008 F250 Pickup											
2011 Intern 7600 Tandem											
2011 Excavator 2012 Intern 7600 Tandem											
1997 Holland Tractor 2020 Ford F150		15,264.00					•				
2013 John Deere Loader		29,500.00									
2016 Ford 1/2 Ton 2015 Mack Tandem											
2015 Mack Tandem 2015 Mack Truck											
2017 Mack Tandem Plow &											
Wing 1996 Volvo/L-70 Loader											
2002 Volve/G740 Grader					213,074.20						

Asset 2014 1/2 Ton Truck Gravel Packer GPS Indicators	2029	2030	2031	2032	2033	2035	2036	2037	2038	<b>2039</b> 20,835.36	2040
Sidewalk Plow blower & broom Sweeper Brush Grader Stoco Shop Furnace Culvert Steamer Culvert Steamer		20,000.00								40,308.15 11,137.40	
Hunt Rd Well - WDS Marlbank Rd Well WDS Weigh scales WDS Compactor 936 Cat WDS Scale Bldg WDS Depot		20,000.00			11,137.40 8,335.24						
2007 JD 605C Crawler Loader								97,587.84			
Total Costs	5,715,221.00	2,402,268.02	1,190,479.00	1,294,259.75	2,575,721.84	60,000.00	1,032,701.86	107,587.84	341,202.00	192,280.91	99,948.80
Gas Tax Funding OCIF Funding	400,041.00 132,396.00	400,041.00 132,396.00	400,041.00 132,396.00	400,041.00 132,396.00	400,041.00 132,396.00		669,208.00 264,792.00		76,410.00 264,792.00		
Other Grants Current Waste Reserve Fund Used Current Road Reserve Used Current Bridge Reserve Used Current Water Reserve Current Sewer Reserve					19,472.64			97,587.84			
Remaining Amounts to be Funded	5,182,784.00	1,869,831.02	658,042.00	761,822.75	2,023,812.20	60,000.00	98,701.86	10,000.00	•	192,280.91	99,948.80
2022 Transfer to Reserves Requirement	647,848.00	207,759.00	65,804.20	69,256.61	168,651.02	4,285.71	6,580.12	625.00	-	10,682.27	5,260.46

Asset	2042	2044	2046	2047	2048	2049	2050	2051	2052
McClellan St - Water McClellan St - Sewer Dowling Bridge Roads - all others noted in AMP									,
Bridges - all others noted in AMP									
Water - all others noted in AMP	30,000.00	10,000.00	60,000.00	20,000.00	40,000.00	140,000.00		90,350.00	60,000.00
Sewer - all others noted in AMP								971,500.00	
Stormwater - all others noted in AMP									
Per TCA (other assets not yet in AMP)									
2 Ton Stoco Garage							102,453.83		
Stoco Sand Dome Maribank Sand Dome			106,106.00						
Countryman Garage Countryman Salt Dome									
Actinolite Garage Actinolite Sand Dome									
Quanset Hut PW Dome 2006 Case/580 Backhoe							53,628.80		
2006 Case/560 Backfloe 2008 550 Ford Dump Truck/Plow									
New Dump truck/plow 2008 Sterling Lt9513 Tandem									
2008 F250 Pickup 2011 Intern 7600 Tandem									
2011 Excavator 2012 Intern 7600 Tandem						•			
1997 Holland Tractor 2020 Ford F150									
2013 John Deere Loader 2016 Ford 1/2 Ton								•	
2015 Mack Tandem 2015 Mack Truck									
2017 Mack Tandem Plow & Wing									
1996 Volvo/L-70 Loader 2002 Volve/G740 Grader									

50,000.00 10,000.00

Asset 2014 1/2 Ton Truck Gravel Packer GPS Indicators Sidewaik Plow blower & broom Sweeper Brush Grader Stoco Shop Furnace Culvert Steamer Culvert Steamer	2042	2044	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
Hunt Rd Well - WDS Marlbank Rd Well WDS Weigh scales WDS Compactor 936 Cat WDS Scale Bldg WDS Depot 2007 JD 605C Crawler Loader	20,000,00	10.000.00	166 106 00	20,000,00	141,733.60	140,000.00	156,082.63	1,061,850.00	60,000.00	12,856.09	50,000.00	10,000.00
Gas Tax Funding OCIF Funding Other Grants Current Waste Reserve Fund Used Current Road Reserve Used Current Bridge Reserve Used Current Water Reserve Current Sewer Reserve	30,000.00	10,000.00	166,106.00	20,000.00	181,733.60 141,733.60					12,856.09		
Remaining Amounts to be Funded  2022 Transfer to Reserves Requirement	30,000.00 1,428.57	10,000.00 434.78	6,644.24	20,000.00 769.23	40,000.00 1,481.48	5,000.00	5,382.16	1,061,850.00 35,395.00	1,935.48	-	50,000.00 1,515.15	294.12

Asset McClellan St - Water	2056	2057	2058	2059	2061	2071	2074	2076	2082	2083	2084
McClellan St - Sewer Dowling Bridge											
Roads - all others noted in AMP											
Bridges - all others noted in AMP											
Water - all others noted in AMP	1,030,000.00	10,000.00	40,000.00	40,000.00			1,000,000.00		1,000,000.00		1,347,437.00
Sewer - all others noted in AMP						5,000,000.00		450,000.00			1,012,468.00
Stormwater - all others noted in AMP										2,330,000.00	

Per TCA (other assets not yet

in AMP)

2 Ton

Stoco Garage

Stoco Sand Dome

Marlbank Sand Dome

Countryman Garage

Countryman Salt Dome

Actinolite Garage

Actinolite Sand Dome

Quanset Hut

PW Dome

2006 Case/580 Backhoe

2008 550 Ford Dump

Truck/Plow

New Dump truck/plow

2008 Sterling Lt9513 Tandem

2008 F250 Pickup

2011 Intern 7600 Tandem

2011 Excavator

2012 Intern 7600 Tandem

1997 Holland Tractor

2020 Ford F150

2013 John Deere Loader

2016 Ford 1/2 Ton

2015 Mack Tandem

2015 Mack Truck

2017 Mack Tandem Plow &

Wing

1996 Volvo/L-70 Loader

2002 Volve/G740 Grader

Asset 2014 1/2 Ton Truck Gravel Packer GPS Indicators Sidewalk Plow blower & broom Sweeper Brush Grader Stoco Shop Furnace Culvert Steamer Culvert Steamer Hunt Rd Well - WDS	2056	2057	2058	2059	<b>2061</b> 17,512.90	2071	2074	2076	2082	2083	2084
Marlbank Rd Well WDS Weigh scales WDS Compactor 936 Cat WDS Scale Bldg WDS Depot 2007 JD 605C Crawler Loader											
Total Costs  Gas Tax Funding OCIF Funding Other Grants Current Waste Reserve Fund Used Current Road Reserve Used Current Bridge Reserve Used Current Water Reserve Current Sewer Reserve	1,030,000.00	10,000.00	40,000.00	40,000.00	17,512.90	5,000,000.00	1,000,000.00	450,000.00	1,000,000.00	2,330,000.00	2,359,905.00
Remaining Amounts to be Funded	1,030,000.00	10,000.00	40,000.00	40,000.00	17,512.90	5,000,000.00	1,000,000.00	450,000.00	1,000,000.00	2,330,000.00	2,359,905.00
2022 Transfer to Reserves Requirement	29,428.57	277.78	1,081.08	1,052.63	437.82	100,000.00	18,867.92	8,181.82	16,393.44	37,580.65	37,458.81

Asset	2085	2088	2089	2090	2098	2099	2101	2102	2106	2107	2108
McClellan St - Water McClellan St - Sewer Dowling Bridge Roads - all others noted in AMP Bridges - all others noted in											
AMP Water - all others noted in			160,650.00		1,500,000.00	258,400.00	430,950.00	204,000.00	774,350.00	197,200.00	527,000.00
AMP Sewer - all others noted in AMP						132,000.00	186,000.00	116,000.00		187,000.00	244,500.00
Stormwater - all others noted in AMP	2,610,000.00	270,000.00		580,000.00							

#### Per TCA (other assets not yet

in AMP)

2 Ton

Stoco Garage

Stoco Sand Dome

Marlbank Sand Dome

Countryman Garage

Countryman Salt Dome

Actinolite Garage

Actinolite Sand Dome

Quanset Hut

PW Dome

2006 Case/580 Backhoe

2008 550 Ford Dump

Truck/Plow

New Dump truck/plow

2008 Sterling Lt9513 Tandem

2008 F250 Pickup

2011 Intern 7600 Tandem

2011 Excavator

2012 Intern 7600 Tandem

1997 Holland Tractor

2020 Ford F150

2013 John Deere Loader

2016 Ford 1/2 Ton

2015 Mack Tandem

2015 Mack Truck

2017 Mack Tandem Plow &

Wing

1996 Volvo/L-70 Loader

2002 Volve/G740 Grader

Asset 2014 1/2 Ton Truck Gravel Packer GPS Indicators Sidewalk Plow blower & broom Sweeper Brush Grader Stoco Shop Furnace Culvert Steamer Culvert Steamer	2085	2088	2089	2090	2098	2099	2101	2102	2106	2107	2108
Hunt Rd Well - WDS Maribank Rd Well WDS Weigh scales WDS Compactor 936 Cat WDS Scale Bldg WDS Depot 2007 JD 605C Crawler Loader										20100000	774 500 00
Total Costs  Gas Tax Funding OCIF Funding Other Grants Current Waste Reserve Fund Used Current Road Reserve Used Current Bridge Reserve Used Current Water Reserve Current Sewer Reserve	2,610,000.00	270,000.00	160,650.00	580,000.00	1,500,000.00	390,400.00	616,950.00	320,000.00	774,350.00	384,200.00	771,500.00
Remaining Amounts to be Funded	2,610,000.00	270,000.00	160,650.00	580,000.00	1,500,000.00	390,400.00	616,950.00	320,000.00	774,350.00	384,200.00	771,500.00
2022 Transfer to Reserves Requirement	40,781.25	4,029.85	2,362.50	8,405.80	19,480.52	5,005.13	7,711.88	3,950.62	9,110.00	4,467.44	8,867.82

Asset  McClellan St - Water  McClellan St - Sewer  Dowling Bridge  Roads - all others noted in  AMP  Bridges - all others noted in	2109	2111	2112	2115
AMP				
Water - all others noted in AMP	1,215,500.00	1,345,550.00		280,500.00
Sewer - all others noted in AMP	673,000.00	783,998.00		156,000.00
Stormwater - all others noted in AMP			10,000.00	

#### Per TCA (other assets not yet

in AMP)

2 Ton

Stoco Garage

Stoco Sand Dome

Marlbank Sand Dome

Countryman Garage

Countryman Salt Dome

Actinolite Garage

Actinolite Sand Dome

Quanset Hut

PW Dome

2006 Case/580 Backhoe

2008 550 Ford Dump

Truck/Plow

New Dump truck/plow

2008 Sterling Lt9513 Tandem

2008 F250 Pickup

2011 Intern 7600 Tandem

2011 Excavator

2012 Intern 7600 Tandem

1997 Holland Tractor

2020 Ford F150

2013 John Deere Loader

2016 Ford 1/2 Ton

2015 Mack Tandem

2015 Mack Truck

2017 Mack Tandem Plow &

Wing

1996 Volvo/L-70 Loader

2002 Volve/G740 Grader

Asset 2014 1/2 Ton Truck Gravel Packer GPS Indicators Sidewalk Plow blower & broom Sweeper Brush Grader Stoco Shop Furnace Culvert Steamer Culvert Steamer	2109	2111	2112	2115
Hunt Rd Well - WDS Marlbank Rd Well WDS Weigh scales WDS Compactor 936 Cat WDS Scale Bldg WDS Depot 2007 JD 605C Crawler Loader				
Total Costs  Gas Tax Funding OCIF Funding Other Grants Current Waste Reserve Fund Used Current Road Reserve Used Current Bridge Reserve Used Current Water Reserve Current Sewer Reserve	1,888,500.00	2,129,548.00	10,000.00	436,500.00
Remaining Amounts to be Funded	1,888,500.00	2,129,548.00	10,000.00	436,500.00
2022 Transfer to Reserves Requirement	21,460.23	23,661.64	109.89	4,643.62

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-310-58131	Vanderwater Road	652,860.00						652,860.00		-	Hwy 37 to Ervine Rd 30 mm Hotmix Everlife
01-310-58131	Queensborough Road	240,000.00		132,396.00				107,140.00		464.00	parking lot with asphalt, gutter, catch basis, 50 mm HL3 Hotmix
01-310-58131	King Street	25,000.00								25,000.00	Queensborough 30mm Everlife Hotmix
01-310-58131	Charles Rd stormwater management	15,000.00								15,000.00	Stage 1 of Jeweil Engineering Proposal
01-310-58131	Sidewalk	8,000.00								8,000.00	50 metres on St. Joseph St where low and holding water/ice
01-310-58131	Victoria Cemetery fencing	17,808.00								17,808.00	
01-310-58132	Tandem Plow/Wing combination	280,000.00				280,000.00				-	Like to purchase new with rent to own option as backhoe needs \$20,000 work on engine
01-310-58132	Backhoe Mower for Holland Tractor Patrol Truck (replace 300) Greatrix Bridge	170,000.00 48,000.00 55,000.00 326,025.00				118,656.34 48,696.00				51,343.66 48,000.00 55,000.00 277,329.00	
01-310-58133	Pre-engineering Joe Allore Bridge	1,946,193.00		132,396,00		108,500.00 555,852.34		760.000.00		497,944.66	-
01-330-58014	GRAVEL PIT Esker Rd Pit Licence	13,590.00 13,590.00	-	-		-	13,590.00 13,590.00	-	•	-	•
01-410-58022	SANITARY SEWER OCWA	16,667.00 16,667.00				16,667.00 16,667.00		-		<u> </u>	
01-420-58023	River Crossing	1,029,682.51	404,800.00	337,333.33		287,549.18				•	Green Stream 2 grant application
01-420-58001 01-420-58001 01-420-58011	Water Tower Interior Coating Water filter media system WATER Water Meters & Hydrants & V	45,000.00 30,000.00				45,000.00 30,000.00				- - -	2 hydrants and shut off valves
01-420-58022	WATER OCWA	25,726.00 1,130,408.51	404,800.00	337,333.33	-	25,726.00 388,275.18			<u>.</u>	<u>.</u>	valves -
01-440-58000 01-440-58000	BluMetric Hunt Road BluMetric Marlbank Road	22,400.00 5,700.00 28,100.00			•		22,400.00 5,700.00 28,100.00	<u> </u>	<u>-</u>	-	





October 1, 2021

Municipality of Tweed 255 Metcalfe Street TWEED, ON KOK 3J0

Attention:

Mr. Allan Broek,

Public Works Manager

RE:

Charles Road - Stormwater Management Plan

**Engineering Services Proposal** 

Jewell Engineering Inc. File No. 210-5025

Mr. Broek:

Thank you for reaching out to us to provide you with a quotation to complete the preliminary design of the stormwater management plan for the Charles Road area. Residents have experienced flooding of their front yards and some basement flooding has also been reported.

As we discussed, the drainage concerns faced by the residents are related to the lack of drainage infrastructure along the roads and more specifically the outlets to Stoco Lake.

A majority of the drainage is currently controlled by a single catch basin with a pipe outlet to Stoco Lake located between two residences. A solution will include expansion of the capacity of this outlet and may also include seeking opportunities for additional outlets.

We would recommend detailed topographic survey be undertaken of the area to include the road, ditches and existing drainage infrastructure, driveways and front yards of the residences. Jewell would review the drainage capacity of the existing infrastructure and propose improvements that may include additional ditching, storm sewers, catch basins and outlets to Stoco Lake.





We will provide you with preliminary drawings with a design concept and estimated costs. Since the preferred solution is not yet known, it is difficult to anticipate what the engineering effort will be to complete final design drawings. There will be an approval required from Quinte Conservation for any solution. We envision that if storm sewers form part of the solution, an application to the Ministry of the Environment for an ECA will be required.

Thus, we suggest the project proceed in three (3) stages.

Stage 1 would be preliminary design. This will include:

- detailed topographic field survey of the ditches, roads, driveways, existing services and front yard areas of the homes,
- hydrologic and hydraulic design with report,
- pre-consultation with approval agencies
- preliminary design drawings, and
- estimate of costs

Jewell would be pleased to also attend a council meeting as the project is presented.

**Stage 2** would include detailed design, approvals and tendering. Another important consideration will be the potential encroachment onto private property. Depending on the outcome of the preliminary design, an OLS may need to be engaged to confirm legal boundaries of properties. We would be able to provide a quotation for stage 2 once we fully understand the level of effort that will be required upon completion of Stage 1.

**Stage 3** would include the Contract Administration and Inspection Phase of the project. The scope of work of this phase and anticipated construction duration will not be known until the completion of design. We would be able to provide a quotation for stage 3 once we fully understand the level of effort that will be required upon completion of Stage 2.



# Stage 1 - Preliminary Design

## 1. Base Plan and Topo Survey

Jewell will complete topographic survey of the Charles Road including centreline, edge of pavement or travelled portion of the road, ditch line and OG shots along the inferred property boundary. We will also locate all driveways and driveway culverts as well as cross culverts including the sizes and inverts. Any aboveground services that are visible will also be picked up including utility poles, guys, and pedestals. Jewell uses precise GPS survey equipment that captures accurate data in three dimensions. The survey data is directly imported into our 3D Civil Design software that is used to create the base drawing.

From the survey data, we will develop contours with intervals of 0.5m (or a smaller interval as the site demands). Where additional topographic information is required, we will supplement our precise survey with Lidar.

#### 2. Stormwater Management Plan

Aided by the grading information, Jewell will review the existing drainage regime and determine weaknesses of the system as well as identify opportunities to improve drainage. We will prepare a preliminary stormwater management plan showing a preferred concept that will be fitting to the locale and present a robust and cost conscious solution.

Jewell will liaise with the Municipality of Tweed and Quinte Conservation Authority in the development of the concept in an effort to find a solution that will be acceptable to the agencies.

Our findings will be published in a letter report.

#### 3. Conceptual Drawings

Preliminary engineering drawings will be prepared showing the existing conditions and the proposed drainage improvements. The drawings will be provided in plan view and will show the land contours, an aerial image, proposed ditching or storm sewer improvements, and all outlets to Stoco Lake.

The drawings will be provided digitally and in hard copy.



#### 4. Cost Estimate

Jewell will prepare an engineer's estimate of the proposed improvements showing the estimated quantities and unit prices.

#### **FEE SCHEDULE**

No.	Task	Estimated Cost
1	Base Plan and Topographic Survey	\$4,500
2	Stormwater Management Plan	\$4,500
3	Conceptual Drawings	\$3,900
4	Cost Estimate	\$1,200
	Total	\$14,100

Additional effort that is required due to revisions or changes to the concept plan will be quoted to the client or if agreed to in advance will be billed on our hourly rates.

#### RATES

All work will be completed at the following standard hourly rates, plus 2% per year starting in 2022. *All costs are exclusive of HST.* 

Staff	Hourly Rate
Company Director	165
Project Lead / Municipal Engineer	100
Senior Water Resources	
Engineer / Project	170
Manager	
Stormwater Engineer	100
Engineer In Training	75
AutoCAD Technician	65
Survey Crew	135
Clerk	65
Inspector	70
Travel	\$0.52/km
Disbursements	At Cost



If you have any questions, please feel free to contact the undersigned.

Sincerely,

Bryon Keene, P.Eng.

Jewell Engineering Inc.

Bym Rune

TWEED CHARLES ROAD SWM CONCEPTUAL DESIGN 2021 SEPT 30



-	-	-	-			m.	170
( 7	к	-	١.	W	16	IV.	10

I, <u>Allan Broek</u>, on behalf of <u>Municipality of Tweed</u>, accept the proposal from Jewell Engineering Inc. to perform the services and terms described in this proposal dated October 1, 2021 based on the rates provided. A signed copy of this proposal returned to Jewell Engineering Inc. shall be considered authorization to proceed.

This proposal is valid for sixty (60) days. Jewell Engineering Inc. reserves the right to renegotiate the terms and conditions of this proposal after sixty (60) days.

•





# Preliminary

Preliminary Pre-Construction Cost Estimate Replacement of Greatrix Bridge Municipality of Tweed

Item	Task Description	Unit	Alternative 1 Precast Concrete Box Culvert			
			Estimated Quantity	Unit Cost	Total Cost	
1	Detailed Design & Engineering	LS	1	\$5,000	\$5,000	
2	Tendering & Contracting	LS	0	\$7,500	\$0	
3	Geotechnical Site Investigation	LS	0	\$10,000	\$0	
4	Environmental Approvals (Additional)	LS	1 -	\$5,000	\$5,000	
5	Construction General Requirements	% of Construction	1	5%	\$12,000	
6	Traffic Control Measures	LS	1	\$5,000	\$5,000	
7	Environmental Protection Measures	LS	1	\$5,000	\$5,000	
8	Existing Bridge Demolition & Removal	LS	1	\$15,000	\$15,000	
9	Site Preparation	LS	1	\$20,000	\$20,000	
10	Utility Relocations	LS	1	\$20,000	\$20,000	
11	6.2m x 15m Precast Concrete Box Culvert Supply & Installation	LS	1	\$150,000	\$150,000	
12	6.2m Span Bridge	LS				
13	Site Restoration & Protection	LS	1	\$15,000	\$15,000	
14	Construction Material Testing	% of Construction	3.0%	-	\$6,750	
P1	Rock Removal (Provisional)	m³				
	Subtotal				\$258,750	
CA1	Contract Administration	% of Construction	5%	-	\$12,938	
	Contingency	% of Subtotal	20%	-	\$54,338	
	Total - High Range				\$326,025	

carried from 2021 - 277.329
(48,696



#### Allan Broek

From:

matt@jewelleng.ca

Sent:

September 16, 2021 3:19 PM pubwks@twp.tweed.on.ca

To: Subject:

Joe Allore Bridge

Hello Al,

Hope you had a great vacation.

I have run some figures on the replacement of the Joe Allore Bridge. Using 2021 construction dollars, I am estimating replacement costs as follows:

#### Replacement with Single Lane Bridge

Construction Cost \$1,250,000 + HST Engineering, EA, Contract Administration & Contingency (25%) \$312,500 + HST

Total Single Lane Bridge Replacement Cost \$1,562,500 + HST

#### Replacement with Two Lane Bridge

Construction Cost \$1,550,000 + HST Engineering, EA, Contract Administration & Contingency (25%) \$387,500 + HST

Total Two Lane Bridge Replacement Cost \$1,937,500 + HST

Should you have any questions or wish to discuss further, please contact me at your convenience.

Regards,

## Matt MacDonald, P.Eng. President



Jewell Engineering 1-71 Millennium Parkway Belleville, ON K8N 4Z5 Phone 613.969.1111 Fax 613.969.8988

# Tweed Victoria Cemetery Board Box 1051, Tweed, Ontario, KOK 3J0

SEP 2 7 2021

Attention: Allan Broek

**Public Works Manager** 

MUNICIPALITY OF TWEED

Greetings Allan,

Have the estimate now from Walsh fencing and have written a letter to the council to go with it. As I had talked to you first I thought it best to give it through you. Please let me know if there is anything further the board or I need to do.

As I did not want my covering letter to be more than a page I did not mention that we had talked about the fact the fence would need to probably be set back a bit more to prevent damage from the sidewalk snowplow. We recognized that it is an ongoing problem hard to prove but certainly there are many dings in the fence consistent with the height of the plow.

Thank you for your attention to this matter. We do appreciate it.

Sincerely, Barbara Goode

Benjara Goods

Dated: September 27, 2021

# Tweed Victoria Cemetery Board Box 1051 Tweed, Ontario, KOK 3J0

# Proposal For New Fence at Victoria Cemetery Tweed Ontario

To Madame Mayor and Municipality of Tweed Councillors,

In July I wrote to Allen Broek on behalf of the Tweed Victoria Cemetery Board to ask what could be done about the fence and the damage that appears to occur from the sidewalk snowplow. This issue was raised at our June 28<sup>th 2021</sup> annual meeting and it was requested that a letter be sent to the municipality. Allen answered immediately and met with myself and my husband to look at the fence. We were very impressed with how helpful he was. On inspection there is lots of damage probably from many years; the fence is very old and in a bad state of repair. He suggested we get some quotes and make a proposal to the municipality.

As I have only been chairperson since May 2018 I made the effort to read through the minutes and information from all the previous years. I discovered that in 1999 a letter was sent to the municipality "regarding damage done to the fence from snow removal by the municipality". That is a direct quote from the minutes. I could not find any answer to that request.

The other interesting fact is that myself and the secretary can not find any documentation that shows who actually owns the cemetery. Two long time board members have opposing views, one thinking it is the board, the other the municipality. I did phone the office to ask that question and have never heard back.

Since being involved with Victoria cemetery I have started to pay attention to all the cemeteries I see. Unfortunately our Victoria cemetery looks rundown because of that old fence. And I am embarrassed by it. We have actually had people who want to buy a plot look at the cemetery and then choose another cemetery they say looks better in a neighbouring location.

The reality is we can not afford to replace the fence. We have \$7,000 in our operating budget and unable to access some savings until October 2022. We have little income but manage with what we get to pay for the superintendent and the grave digging. This past year we have not sold any plots and that is one source of income.

We are wondering if there are any grants available or we partner with several parties to pay for the fence. We only have one quote but Walsh are the main fence people and it is very reasonable. Also the fencing material they use now is coated so no need for repainting and no rust problems.

Please find enclosed the quote from Walsh fencing. I look forward to further conversation.

Sincerely, Barbara Goode, Chair Tweed Victoria Cemetery board. Dated September 26, 2012

Barbara Goode

# JOB ESTIMATE

1743131 UNTARIO LI D.	DATE: 13-3ep-21	
A WALSH FENCING		
1021 HWY 37, RR # 1		
CORBYVILLE, ON KOK 1VO		
PHONE: 613.962.2261 FAX 613.968.8957		
walshfencing@bellnet.ca		
		-
TO: Don Sedore		
6711 Hwy 37		
Tweed, ON KOK 3J0		
P- 613 478 3275	NO EMAIL	
		·
DESCRIPTION:		•
DESCRIPTION.		
LOCATION: Victoria Cemetery		
Install 750' of 4' all white or black chain link, 9 gau	uge mesh, residential frame, (1)	single
vehicle gate and (1) double vehicle gate. Take do	wn and dispose of old fence.	
· · · · · · · · · · · · · · · · · · ·		
·		
TOTAL MATERIAL & LABOUR \$17,500.00		
1017L WW. LAWAL & LABOOK		
13% HST \$2,275.00		
TOTAL ESTIMATE \$19,775.00		
HST 82275 2820 RT0001		
AUTHORIZATION TO PROCEED :		
DATE		1
Joe/09 sept 21 Customer Signature		



20 Private Road, RR # 2

Marmora, ON

KOK 2MO

Phone: (613) 472-2131

Fax: (613) 472-6045

October 28, 2021

Allan Broek, Public Works Manager, Municipality of Tweed 255 Metcalf Street Postal Bag 729 Tweed, ON KOK 3J0

Dear Mr. Broek,

#### RE: 2022 Capital & Major Maintenance Expenditure Recommendations

On behalf of the Ontario Clean Water Agency (OCWA), we have enclosed a rolling six-year list of major maintenance recommendations as per our Services Agreement. OCWA suggests the following improvements/upgrades to ensure the long-term health and operation of your facilities.

Please note that as per the requirements of the Drinking Water Quality Management Standard (DWQMS), the outcomes of the risk assessment conducted for your water and wastewater facilities were considered and any related items have been included in the recommendations.

We would be happy to meet with you to discuss the recommendations, projected expenses, and assist with selecting the best course of action.

Thank-you,

Amber Coupland
Operations Manager
Deloro Cluster

Ontario Clean Water Agency

Ph. 613-472-2131 ext 3

Cell. 613-921-3989

cc:

Gloria Raybone, CPA, CA, CAO/Treasurer, Municipality of Tweed



20 Private Road, RR # 2 Marmora, ON

K0K 2M0

Phone: (613) 472-2131

Fax: (613) 472-6045

files,	Scape of Work	2502	2 (1023)	2/5/241	2028	2(8)25	2007
	Tweed Water						
1	Annual UV Maintenance	\$1,457	\$1,486	\$1,516	\$1,546	\$1,577	\$1,609
2	Annual Lifting Device Inspections	\$955	\$974	\$994	\$1,013	\$1,034	\$1,054
3	Annual Flow Meter Calibrations	\$1,040	\$1,061	\$1,082	\$1,104	\$1,126	\$1,148
4	Annual Diesel Maintenance	\$911	\$929	\$948	\$967	\$986	\$1,006
5	Annual Backflow Preventer Inspections	\$213	\$217	\$222	\$226	\$231	\$235
6	Trojan Reference Sensor and UV Parts	\$5,030	\$3,121	\$3,183	\$3,247	\$3,312	\$3,378
7	De-chlor pucks	\$510	\$520	\$531	\$541	\$552	\$563
8	Load of Salt (Brine Solution)	\$0	\$0	\$0	\$0	\$16,000	\$0
9	Chlorine Parts and Maintenance	\$5,610	\$5,722	\$5,837	\$5,953	\$6,072	\$6,194
10	Replace Three Hydrants in Town	**	**	**	**	**	**
11	Repair Five Leaking Hydrants	**	**	**	**	水水	**
12	Water Tower Internal Re-coating			\$650	,000		
13	Water Treatment Plant Media Replacement	\$45,000	\$0	\$0	\$0	\$0	\$0
14	Contingency to Cover Unexpected Breakdowns	\$10,000	\$10,000	\$10,000	\$10,000	\$10,000	\$10,000
	Total Estimate - Recommended Capital	\$70,726	\$24,080	\$24,313	\$24,597	\$40,890	\$25,187

Mon	Scippe of Work	2022	2002	2024	2025	2026	2027
	Tweed Wastewater						
1	Annual Lifting Device Inspections	\$874	\$892	\$909	\$928	\$946	\$965
2	Annual Flow Meter Calibrations	\$936	\$955	\$974	\$993	\$1,013	\$1,033
3	Annual Wetwell Cleanouts	\$2,155	\$2,198	\$2,242	\$2,287	\$2,333	\$2,380
4	Annual Diesel Maintenance	\$1,280	\$1,306	\$1,332	\$1,358	\$1,385	\$1,413
5	pH Probe and Buffers	\$422	\$430	\$439	\$448	\$457	\$466
6	Lagoon Annual Blower Maintenance	\$1,000	\$1,020	\$1,040	\$1,061	\$1,082	\$1,104
7	SPS Tree & Brush Removal	**	**	**	**	**	**
8	Contingency to Cover Unexpected Breakdowns	\$10,000	\$10,000	\$10,000	\$10,000	\$10,000	\$10,000
	Total Estimate - Recommended Capital	\$16,667	\$16,801	\$16,936	\$17,075	\$17,216	\$17,360



2302 Dumfries Rd., Unit A4, Cambridge, On., N1R 5S3 Tel. 519.389.8542 / 519.389.8549 Fax. 519.488.1081

## Tweed Elevated Tank Video Inspection



Client

**OCWA** 

Representative: Amber Coupland, Operations Manager

Project

Internal video inspection and external visual, where accessible.

Method

Potable water-dedicated video ROV with colour camera and lighting.

Object

Elevated steel tank, full of water and in-service

Location

Tweed, ON

Date

July 28, 2020

AIS Job no.

20200128-01-OCWA

Prepared by: Paul Keenan



## TABLE OF CONTENTS

		Page
1.0	Introduction	3
2.0	Equipment	3
3.0	Conclusions	3
4.0	Recommendations, Inspection/Discussion	3-4
5.0	Photos & Underwater Images	4-9

2302 Dumfries Rd., Unit A4, Cambridge, On., N1R 5S3

Tel. 519.389.8542 / 519.389.8549 Fax. 519.488.1081

ISO 9001:2015 Registered

#### 1.0 Introduction:

At the request of the Ontario Clean Water Agency, as part of normal due diligence and routine maintenance, an underwater video survey, using a disinfected submersible ROV with lighting and high-resolution camera, was performed inside the Tweed elevated, steel water tank, while in-service and full of water. The disinfection of the ROV and umbilical cable was performed immediately prior to entering the elevated tank using sodium hypochlorite and potable water supplied by OCWA personnel.

The main reasons for the survey were to check the overall internal condition of the tank coating and components, type and amount of floor sediment and identify any other anomalies while leaving the tank on-line and full of water. The entire video survey was recorded and a copy of the video, in computer media format, is supplied with this report.

## 2.0 Equipment:

Submersible video ROV with high-resolution tilt camera and lighting.

#### 3.0 Conclusions:

- 3.1 There are areas of coating failure on the internal tank walls, topside of the tank floor hatchway, surface of the dry riser, overflow opening and underside of tank roof.
- 3.2 There is very little sediment seen on the floor but there is dark staining at the water level fluctuation zones on the tank and dry riser.
- 3.3 The roof top vent screening assembly and other roof top items appear in good condition.
- 3.4 The external tank coating appears in good condition. Some growth deposits are seen on the underside of the angled section of steel plating.

#### 4.0 Recommendations:

- 4.1 OCWA personnel to review the inspection video and this report.
- 4.2 Plan to surface prep and recoat the internal surfaces of this tank, including the floor bottom hatch cover.
- 4.3 Request from AIS NDE information on other services relating to tank recoating using NACE approved coatings, above and below ground piping inspections, for example.



## 5.0 Inspection/Discussion:

The potable water dedicated video ROV and umbilical were disinfected, immediately prior to entering the tank, using sodium hypochlorite and potable water supplied by OCWA operations then lowered into the top of the elevated tank through the square roof top hatchway adjacent to the access ladder. The ROV was "flown" to areas of interest to view the floor, inlet-outlet nozzle, underside of tank roof structure, dry riser, tank walls and floor hatchway.

This is a brand-new submersible video inspection ROV and so movements around the inside of the tank were made using extreme caution so there was no chance of entangling the ROV and cable. There are two video files; 1<sup>st</sup> file begins at clock-time 12:08:30 and the 2<sup>nd</sup> file begins at 12:38:55. Suggest the viewers of the video use "fast-forward" to move through footage to areas of interest.



Roof top vent assembly in good condition



Underside of roof structure viewed from manway



Roof top vent screening from another angle




View down at dry riser and overflow from roof




20,1100 11

Typical internal wall view of coating failures



Tank roof hatch closed and secured after survey




Random section of tank roof; coating in good condition



Tank roof hatch opened to allow ROV access



Dry riser hatchway open for roof access



Another random view of tank roof plating



BUT PERSON THE SE

View directly up dry riser; roof hatch secured



Underside of tank floor hatch



Overflow piping and inlet-outlet pipe section



View straight down the dry riser and ladder



Top end of ground to catwalk ladder



Catwalk and bottom of roof access ladder





Pulley used for hoisting equipment to tank catwalk

Overall view - looking up - of concrete structure





Overall view of underside of tank roof structure

Inlet-outlet pipe, hatch cover, thin sediment layer






View up dry riser and attached overflow opening

Coating failure at the water level fluctuation zone








Coating loss at dry riser bottom, thin layer of sediment


Coating failure on dry riser





Areas of coating failure on upper areas of dry riser

Typical section of wall to roof intersection






Staining on dry riser at water level fluctuation zone

Straight down, wide view of tank floor









Wide view of floor and lower dry riser



Residue and "growth" deposits under angled section



Tower skirt entry door secured after survey



27 October 2021

Mr. Allan Broek
Public Works Manager
Municipality of Tweed
255 Metcalf Street
Tweed, ON KOK 3J0

RE:

Annual Monitoring & Reporting, Engineering Services & Contingency Work

Dear Allan:

This letter is to provide you with the "budgetary" costs for the 2022 annual monitoring and reporting work on the Municipality of Tweed's Waste Disposal Sites (WDSs) and Public Works Yard. In addition, it provides budget information for items that are proposed for closure, follow-up for remediation work, and potential mitigation measures/contingency work.

Please note that I have currently added 20% for increases to personnel charge out rates and for analytical costs. As you know inflation has been increasing and is expected to do so, and employment costs have seen a significant increase over the last year. None of these rates have been determined for 2022 yet, and we are expected to have more refined costs in the later parts of 2021 or early 2022. The analytical testing laboratories have already notified us that are anticipating increases for 2022 but have not put any numbers to that yet.

#### Annual Monitoring & Reporting

The 2022 annual budgets for monitoring and reporting and for advice on operational issues for the Municipality's WDSs are \$20,400 for Hunt Road and \$29,400 for Marlbank Road. As mentioned, we will revisit this once 2022 rates are available and aim to come up with lower budgets if possible.



## Additional Work to the Typical Annual Monitoring & Reporting

The above budget estimates are for the traditional annual monitoring and reporting. The following additional costs are included in the 2022 work:

#### Hunt Road WDS

- Potential additional contingency sampling at Hunt Road WDS assumed for one event (\$4,200), this work was not required in 2021.
- Following approval of the Site Closure Plan by the MECP, prepare the tender documents for the work to be carried out by a private contractor, if not to be carried out directly by Municipal workers (\$10,000). This cost does not include assistance with the tendering, construction oversight during the closure work, over final reporting on the actual closure work completed. It is assumed that the actual closure work will be carried out in 2023.
- Attend one meeting with the landowners adjacent to the Site to inform them of the requirements for the Contaminant Attenuation Zone (CAZ) around the Site (\$6,200). This work was not carried out in 2021, we have moved it forward to the budget for 2022 if required.
- Answer questions from the Municipality about Land Registry Requirements for Hunt Road WDS, if required (\$2,000). Does not include costs for legal fees, surveys etc.

## Marlbank Road WDS - Contingency Sampling and Additional Work to Address RUV Exceedances

Surface water contingency sampling was required in 2018 but was not required in 2019, 2020, or 2021. An amount of \$4,200 is being carried in case it is required for an assumed one event in 2022.



### Marlbank Road Public Works – Final Verification Sampling & Spill Response Plan

Work remaining and recommendations were provided in BluMetric's environmental sampling at the Public Works Yard at Marlbank Road. As indicated in the email from the MECP inspector (14-Jun-2021). The following work must be completed:

Once water is present in the ditch, one additional round of surface water samples (2 samples plus QA/QC) are to be collected in the spring of 2022 to assess potential for ongoing fuel-related impacts. Samples should be tested for PHCs and BTEX. The results must be reported to the MECP. A budget price for this work has been estimated to be (\$1,500).

The following recommendations were made with respect to the above work:

- Preventative measures, for example, CSA approved storage bins, drip trays, or other secondary containment) should be considered to prevent future potential spills.
- The Municipality should have a Spill Action Plan developed for the Site and train Municipal staff to follow the procedures outlined in the Spill Action Plan.

If the Spill Action Plan has not already been carried out and you would like BluMetric to do an inventory of the fuel, fuel equipment, and other hazardous materials on-site in 2022 and prepare a Spill Action Plan for the Site we are prepared to carry out this work for \$5,000. Should the Municipality just need an inventory of the fuel, fuel equipment and Spill Action Plan without consideration for other hazardous material it could be reduced to \$3,000. We are assuming the training of Municipal personnel will be carried out by others.

#### Summary of Annual Monitoring and Reporting Costs

Table 1 provides a summary of budget estimates for work that we anticipate have a potential to be required in 2022. These costs do not include HST.



OPERING Expenses

Table 1: Annual Monitoring and Reporting Costs

Site	Annual Monitoring/Report/Engineering Services	Totals
Marlbank Rd	24,000	
Hunt Rd	20,400	a marketing
2021 Annual Monitoring		\$44,400
	Hunt Road Additional Work	
Potential Contingency Sampling	\$4,200	
Prepare Tender Documents for Site Closure	\$10,000 (end of 2022- beginning of 2023)	
Meeting with Landowners	\$6,200	
Assistance with Land Registration	\$2,000	\$
zana regionation		\$22,400
	Maribank Road WDS Additional Work	
Potential Contingency Sampling	\$4,200	\$4,200
	Marlbank Road Public Works Yard Additional Work	
Additional Verification SW Samples & Report	\$1,500	
Inventory of Materials and Spill Action Plan	\$5000 I Have our Still action Pla	2 own
	25:11 acrive ple	\$6,500
		\$77,500

We assume that the Letter for the Auditors & Updated Closure Costs \$2,000 will not be required in 2022.

Thank you again for this opportunity to provide you with a cost estimate for the 2022 Annual Monitoring and Reporting. We welcome the opportunity to continue our working relationship with the Municipality of Tweed.

Please feel free to call the undersigned if you have any questions at (613) 531-2725 ext. 245, or Cell 613-238-0423.

Respectfully submitted,

BluMetric Environmental Inc.

Iris O'Connor, P.Eng.

Project Engineer





# Asset Management Plan Report Version 1.2

Municipality of Tweed
County of Hastings, Ontario

Version 1.2:

August 31, 2021

Version 1.1:

June 28, 2021

Version 1.0:

December 06, 2019

VCISIOII 1.0.

Greenview File: 169.21.003







## **Table of Contents**

0.1	Introduction	_1
1.1	Municipal Information	1
1.2	Purpose and Scope (Updated August 2021)	1
2.0	State of Local Infrastructure	_2
2.1	Table Summary (Updated August 2021)	
2.1.1	Table 1 – Municipal Study Area Characteristics	
2.1.2	Tables 2a/2b/2c/2d/2e - Core Asset Summary Tables (Updated August 2021)	
2.1.3	Table 3a – General Summary of Municipal Assets (Updated August 2021)	
2.1.4	Tables 3b and 3c – Municipal Reserves (Updated August 2021)	
2.1.5	Tables 4a/4b/4c/4d/4e - Detailed Summary of Municipal Assets (Updated August 2021)	4
2.1.6	Tables 5a/5b/5c/5d/5e - Financial Assessment and Projections (Updated August 2021)	4
2.1.7	Tables 6a/6b/6c/6d/6e - Priority Assets Recommended for Further Review (Updated August 2021)	) . 5
2.2	Definitions (Updated June 2021)	5
2.3	Proposed Data Verification and Condition Assessment Policy	6
2.4	Roads	6
2.5	Bridges and Large Culverts	8
2.6	Water Supply Services (Updated August 2021)	9
2.7	Wastewater Services	. 10
2.8	Stormwater Assets (New June 2021)	. 11
3.0	Current Levels of Service (Updated August 2021)	_13
3.1	Roads	
3.2	Bridges and Large Culverts	. 14
3.3	Water Supply Services	. 14
3.4	Wastewater Services	. 14
3.5	Stormwater Assets (New June 2021)	. 14
4.0	Procurement and Options Analysis	_15
4.1	Procurement Methods	. 15
4.2	Options Analysis Review (Updated June 2021)	. 15
5.0	Financial Strategy	_17
5.1	Summary and Definitions (Updated August 2021)	
5.2	Integration with Municipal Budgets,	. 18



5.3	Maintenance Versus Upgrade/Replacement of Assets	18
5.4	Assumptions on Future Changes in Population and Economic Activity	18
5.5	Detailed Risk Assessments and Asset Management Planning Activities	
5.6	Determination of Priority Assets for Replacement/Upgrade (Updated June 2021)	
6.0	Priorities and Recommendations (Updated August 2021)	21
6.1	Roads	21
6.1.1	HCB Road Sections	21
6.1.2	LCB Road Sections	
	Gravel Road Sections	
6.1.3		
6.2	Bridges and Large Culverts	
6.3	Water Supply Services (Updated August 2021)	23
6.4	Wastewater Services	25
6.5	Stormwater Assets (New June 2021)	27
6.6	Coordination of Asset Replacements/Upgrades (Updated June 2021)	28
6.7	Recommendations for Future Asset Management Planning Activities (Updated	
7.0	Closing	29
8.0	Selected References	30
List	of Tables	
Table	1 Municipal Study Area Characteristics	
Table		
Table	2b 2019 Bridges and Large Culvert Summary	
Table	2c 2019 Water Supply Services Summary	*Updated - August 2021*
Table	2d 2019 Wastewater Services Summary	
Table	2e 2020 Stormwater Asset Summary	*New - June 2021*
Table	3a General Financial Summary of Municipal Assets	*Updated - August 2021*
Table	Bb Municipal Reserves and Allocation Summary	*Updated - August 2021*
Table	Bc Detailed Municipal Reserves Allocation Calculations	*Updated - August 2021*
Table	The contract of the contract o	
Table	4b Detailed Summary of Municipal Assets (Bridges and Large Culverts)	
Table	Detailed Summary of Municipal Assets (Water Supply Services)	*Updated - August 2021*
Table	Detailed Summary of Municipal Assets (Wastewater Services)	
Table		*New - June 2021*
Table	Financial Assessment and Projections (Roads)	
Table		
Table	• • • • • • • • • • • • • • • • • • • •	*Updated - August 2021*
Table	Financial Assessment and Projections (Wastewater Services)	
Table	5e Financial Assessment and Projections (Stormwater Assets)	*New - June 2021*



Municipality of Tweed

Table 6a	Priority Assets Recommended for Further Review (Roads)	
Table 6b	Priority Assets Recommended for Further Review (Bridges and Large Culve	erts)
Table 6c	Priority Assets Recommended for Further Review (Water Supply Services)	*Updated - August 2021*
Table 6d	Priority Assets Recommended for Further Review (Wastewater Services)	
Table 6e	Priority Assets Recommended for Further Review (Stormwater Assets)	*New - June 2021*

## List of Appendices

Appendix A Ontario Regulation 588/17 - Asset Management Planning for Municipal Infrastructure

Appendix B Statement of Service Conditions and Limitations



#### 1.0 Introduction

#### 1.1 Municipal Information

The Municipality of Tweed (Municipality) is an amalgamated municipality in southern and central Hastings County, Ontario, comprised of the former geographic Township of Grimsthorpe, Township of Elzevir, Township of Hungerford, and the Village of Tweed.

Based on 2016 Census data (Statistics Canada, 2019), the Municipality had a population of 6,044 (Table 1). Per 2016 Census data (Statistics Canada, 2019), the land area of the Municipality was approximately 953 square kilometres (km²); however, based on mapping data provided by the County of Hastings (2019), the land area of the Municipality, including the geographic Township of Grimsthorpe, Elzevir, and Hungerford (and the Village of Tweed) was approximately 975 km². For the purposes of this study, the approximate land area of 975 km² has been used. The Municipality's population density per km² is reportedly 6.3, based on Statistics Canada's reported land area, and 6.2 based on the County of Hastings reported land area. As of 2016, there were reportedly 3,023 private dwellings within the municipality, with 2,569 dwellings occupied by usual residents.

The Municipality's operating budget in 2018 (total municipal expenditures) was approximately \$6,800,000.

This Asset Management Plan (AMP; Version 1.2) Report has been prepared in general accordance with the requirements of Ontario Regulation (O.Reg.) 588/17 – Asset Management Planning for Municipal Infrastructure (Appendix A).

#### 1.2 Purpose and Scope (Updated August 2021)

This AMP Report is intended to be a resource tool for the Municipality in decision-making processes with respect to the quantification, management, maintenance, upgrade, and replacement of municipal infrastructure and assets, to assess how assets are managed in a way that continues to provide the current level of service expected by the Municipality and its ratepayers in future, and provide a financial assessment of municipal assets with a focus on the five (5) and ten (10) year planning horizon, and with consideration of a thirty (30) year and total life expectancy planning period. This AMP Report is a tool to be reviewed concurrently with municipal budgets, financial reports, financial information returns, audited tangible capital asset reports, and any other reports or documents relevant to municipal asset management and infrastructure project planning.

The purpose of this AMP Report is to summarize the work completed by the Municipality in 2019 with respect to asset management planning (Version 1.0 of AMP; Greenview, 2019d), with a specific focus on meeting (or exceeding) the requirements of O.Reg. 588/17 (Appendix A), as well as to integrate work completed in 2020/2021 with respect to Stormwater Assets (Version 1.1 of AMP; Greenview, 2021b) and to update specific Water Supply Services assets (Version 1.2 of AMP). The Province of Ontario's requirements for an AMP were first published in the document entitled *Building Together – Guide for Municipal Asset Management Plans* (Guide; Ministry of Infrastructure, 2012), and this AMP Report has been prepared with consideration of the requirements of the Guide, in addition to O.Reg. 588/17.

The scope of this AMP Report (Version 1.2) is consistent with the requirements of the Guide (Ministry of Infrastructure, 2012), and the selected core asset categories as prescribed by the Municipality for this project. With respect to the requirements of O.Reg. 588/17, this AMP Report (Version 1.2) includes the review of all core municipal assets. The scope of this AMP Report (Version 1.2) includes the following applicable core asset categories:

- 1. Roads.
- 2. Bridges and Large Culverts.
- 3. Water Supply Services (Updated August 2021).
- 4. Wastewater Services.
- 5. Stormwater Assets (New June 2021).



#### 2.0 State of Local Infrastructure

The following sections are intended to provide a summary of the detailed review of municipal core assets including:

- 1. Table Summary.
- 2. Definitions.
- 3. Proposed Data Verification and Condition Assessment Policy.
- 4 Roads
- 5. Bridges and Large Culverts.
- 6. Water Supply Services (Updated August 2021).
- Wastewater Services.
- 8. Stormwater Assets (New June 2021).

#### 2.1 Table Summary (Updated August 2021)

In 2019, 2020, and 2021, Greenview Environmental Management Limited (Greenview) completed a detailed review of all core assets, including roads, bridges and large culverts, water supply services, wastewater services, and stormwater assets for the Municipality. Reviews of related documents and data sources were completed by Greenview, including:

- Mapping data for the road, water and wastewater systems, and stormwater assets of the Municipality available from the County of Hastings.
- 2018 OSIM Bridge Inspection Report, and related documents on bridges and large culverts in the Municipality, as prepared by Jewel Engineering Inc.
- Historical drinking water system reports for the Municipality's water supply system, as prepared by the Ontario Clean Water Agency (OCWA).
- Historical drinking water system inspection reports for the Municipality's water supply system, as prepared by the Ontario Ministry of the Environment, Conservation, and Parks (MECP).
- 5. Other drinking water system-related documents (as were available).
- 6. Historical wastewater reports for the Municipality's wastewater system, as prepared by OCWA.
- Environmental Compliance Approvals (ECAs) for various components of the Municipality's wastewater services.
- 8. Other wastewater system-related documents (as were available).
- 2018 Tangible Capital Assets Report and 2018 Continuity of Reserves and Reserve Funds, as prepared by Baker Tilly KDN LLP.
- Field observation and topographic surveying of pertinent stormwater asset infrastructure to assess resiliency of stormwater infrastructure.
- 11. Assessment of authority flood mapping as it relates to flooding potential in the Municipality.
- 12. Other historical Municipal information, as may have been available.

Additionally, multiple in-person and teleconference meetings were held with Public Works staff and Greenview, to discuss any gaps in data that became apparent though the development of this AMP Report (Versions 1.0, 1.1, and 1.2).

The focus of much of the work related to the AMP Report (Version 1.0; Greenview, 2019d) concentrated on Tables 4a to 4d (Detailed Summary of Municipal Assets) and on Tables 5a to 5d (Financial Assessment and Projections), while the focus of AMP Report (Version 1.1) was to integrate new information on stormwater assets into the AMP (Tables 4e and 5e). As part of this AMP Report (Version 1.2), specific updates were applied to water supply services Asset IDs WS21-76 and WS21-88 and related tables.

The following sub-sections describe each of the relevant Table sets of this AMP Report (Version 1.2).



#### 2.1.1 Table 1 - Municipal Study Area Characteristics

Table 1 – Municipal Study Area Characteristics summarizes specific municipal characteristics available from Statistics Canada and from the County of Hastings, including current population, households, land area, and population density. This table was included in the AMP Report in order to provide additional context to the Municipality's core assets.

## 2.1.2 Tables 2a/2b/2c/2d/2e - Core Asset Summary Tables (Updated August 2021)

Tables 2a, 2b, 2c, 2d, and 2e are summary tables that have been prepared in order to easily identify pertinent asset management planning details for the Municipality, including data that specifically is reported in order to satisfy Community Level of Service (qualitative descriptions) and/or Technical Levels of Service (technical metrics) requirements of O.Reg. 588/17.

#### 2.1.3 Table 3a - General Summary of Municipal Assets (Updated August 2021)

Table 3a – General Summary of Municipal Assets is a summary of the financial assessment and projections from Tables 5a to 5e for the core assets of the Municipality.

Table 3a includes the dollars available from current municipal reserve accounts recommended to be applied to pertinent assets (in column "2019"), and recommendations for municipal dollars to be saved in applicable reserve accounts in Years 2 through 10, in order to replace/upgrade assets in specific asset categories at the end of their useful lifespan.

Table 3a also includes columns that sum the municipal reserve dollars required to replace/upgrade assets in each asset category for a Total – 10 Year, Total – 30 year, and Total Required Reserve (Replacement Cost) perspective.

Additionally, the Estimated Borrowing Cost and the Difference between borrowing money to replace/upgrade assets and saving municipal reserve dollars for the replacement/upgrade of assets has also been calculated, based on Infrastructure Ontario's lending rate as of July 8, 2019 on Tables 5a to 5d, and the lending rate as of June 23, 2021 for Table 5e.

#### 2.1.4 Tables 3b and 3c - Municipal Reserves (Updated August 2021)

Tables 3b and 3c are tables that are specific to the Municipality's reserve accounts.

As part of the AMP Report (Version 1.0; Greenview, 2019d), Tables 3b (Municipal Reserves and Allocation Summary) and 3c (Detailed Municipal Reserves Allocation Calculations) were created in an effort to correlate current Municipal reserves that would apply to each asset category. Current reserves were divided into reserves that are applicable to the AMP and to reserves that are not applicable to the AMP. Reserves that were applicable to the AMP, whether directly to specific assets categories, operating departments, or specific assets, or generally to asset categories, were used to reduce the Projected Contributions to Reserves in Tables 5a to 5d. As part of Version 1.1 of the AMP, stormwater assets we added to Tables 3b and 3c; however, no specific funds were included to stormwater related assets as no known funds were understood to be allocated within municipal reserves specific to stormwater assets. Minor changes were applied to Tables 3b and 3c as part of Version 1.2 of the AMP with respect to the specific changes to Asset IDs WS21-76 and WS21-88 and related tables.

On Table 3b – Municipal Reserves and Allocation Summary, current reserves are apportioned to municipal asset categories, either specifically if the reserve account is specific to a particular asset type or non-specifically if the reserve account is related to a general asset category. For example, the Municipality has a reserve account named "Public Works – Bridges" and the funds in that account have been divided between the Municipality's bridges and large culverts based on the total replacement/upgrade cost of both asset types.

Table 3c - Detailed Municipal Reserves Allocation Calculations is related to Table 3b, such that it describes in



detail exactly how Municipal reserves have been, or not been, applied to Municipal core assets. It details a Summary of Reserves Applicable to Core Assets and a Summary of Reserves Not Applicable to Core Assets.

The intent of Table 3c is to provide the reader of the AMP Report with more detailed information about the allocation of Municipal reserves as well as providing context and direct linkages between the AMP Report and the Municipality's annual Continuity of Reserves and Reserve Funds and the annual Consolidated Financial Statements, as prepared by the Municipality's auditors.

## 2.1.5 Tables 4a/4b/4c/4d/4e - Detailed Summary of Municipal Assets (Updated August 2021)

Tables 4a (Roads), 4b (Bridges and Large Culverts), 4c (Water Supply Services), 4d (Wastewater Services), and 4e (Stormwater Assets) have been prepared in general accordance with O.Reg. 588/17 – Asset Management Planning for Municipal Infrastructure and Building Together – Guide for Municipal Asset Management Plans (Guide; Ministry of Infrastructure, 2012).

Asset-specific information is included based on the asset category in question; however, Tables 4a/4b/4c/4d/4e all include general asset information like Asset ID, Asset Name, Year in Service, Asset Life Expectancy, Projected Replacement or Upgrade Year, details from the Municipality's Tangible Capital Asset Report (as applicable and as available), Replacement and/or Maintenance Cost (or equivalent), Condition Rating, and Current Level of Service.

## 2.1.6 Tables 5a/5b/5c/5d/5e - Financial Assessment and Projections (Updated August 2021)

Tables 5a (Roads), 5b (Bridges and Large Culverts), 5c (Water Supply Services), 5d (Wastewater Services), and 5e (Stormwater Assets) have been prepared in general accordance with O.Reg. 588/17 – Asset Management Planning for Municipal Infrastructure and Building Together – Guide for Municipal Asset Management Plans (Guide; Ministry of Infrastructure, 2012).

Tables 5a/b/c/d/e have been provided in order to itemize the amount of money required to be put into reserves on an annual basis for each asset in order to replace/upgrade each asset at the end of their remaining useful life. Values included in the column for "2019" represent the current reserve values calculated for each asset, based on known 2018 reserve fund values as prepared by the Municipality's auditors (as shown in the column "Current Reserves 2018). Similarly for updates related to stormwater assets are included starting with the year "2021" on Table 5e. The column on Tables 5a/b/c/d/e named "Reserve Planning Balance" has been designed to take the values identified in the column "Current Reserves (2018) and subtract that value from "Reconstruction/Rehabilitation Cost" in the case of road assets, "Total Upgrade Cost " in the case of bridge and large culvert assets, and from "Replacement and/or Upgrade Cost" in the case of water supply services and wastewater services assets. Updates to the AMP tables and report related to more recent Tangible Capital Asset Reports and related municipal reserves were beyond the scope of Versions 1.1 and 1.2 of the AMP Report, which was focused solely on the addition and incorporation of stormwater assets to the AMP Report (Version 1.1) and minor changes to Asset IDs WS21-76 and WS21-88 (Version 1.2). Future AMP updates can consider overall updates of this nature.

Additionally, the "Total Reserve (30 Year)" and "Total Required Reserve" have been reported for each specific asset, as well as a column that indicates the "Estimated Borrowing Cost" for replacement of each asset based on current lending rates from Infrastructure Ontario (IO), as of July 8, 2019. The lending rate as of June 23, 2021 was also included for Table 5e. The difference in cost between borrowing and saving sufficient monies for asset replacement is indicated in the column "Difference (Borrowing – Savings)".

Given the significant cost of many of the core assets from a replacement or upgrade perspective, it is unlikely that all of the noted assets with a Projected Replacement or Upgrade Year of 2019 (or previous), or a poor condition rating, can be replaced/upgraded at the time of the noted Upgrade Year. It is recommended that the Municipality determine the priority status of replacement or upgrade for each of the noted assets based on the condition rating, current level of service, available funding options, and capital budgets. Consideration of



alternative maintenance options that could extend the asset life expectancy or improve the condition rating of each asset, and/or alternative funding opportunities are recommended to be investigated, in particular for the very high-value assets.

#### 2.1.7 Tables 6a/6b/6c/6d/6e - Priority Assets Recommended for Further Review (Updated August 2021)

Tables 6a/6b/6c/6d/6e have been prepared to provide a summary reference for any assets that have been recommended as priorities for further review, upgrade, or replacement by the Municipality as part of their asset management planning initiatives.

Details on assets recommended for further review are included in Section 6.0 – Priorities and Recommendations of the AMP Report Version 1.2.

#### 2.2 Definitions (Updated June 2021)

The following is a select list of definitions which explain some elements of the Detailed Summary of Municipal Assets Tables (4a to 4e), for review considerations. In cases where the definition of a specific element was understood to be self-evident, they were not included below.

Item	Definition	Example
Asset ID	An Asset ID tag was assigned to each asset to allow for easier reference and sorting purposes. The year the Asset ID was created is included in the naming convention.	<ul><li>Roads = R19-01</li><li>Stormwater Assets = STW20-06</li></ul>
Detailed Asset Description	Used to describe assets that share similar characteristics with each other.  Detailed Asset Descriptions vary dependent on asset groups.	LCB (low class bituminous pavement)     Bridge
Geographic Township	Used to define the location of the asset in the Municipality.	Hungerford, Elzevir, Grimsthorpe
Year in Service / or Last Upgrade Year	Age of the asset, year asset was purchased, the year the asset was put into service, or the year the asset was last upgraded.  Year in Service is always a "year".	• 2015
Asset Life Expectancy	The number of years the asset is anticipated to be useful/functional.	Bridges = based on OSIM reports Roads = based on estimates and PCI values Water/Wastewater/Stormwater assets - based on estimates of the Municipality, information from OCWA, and/or industry standards
Projected Replacement or Upgrade Year	The year an asset should be replaced and or upgraded. Estimated based on the sum of the current year and Asset Life Expectancy.	<ul> <li>Alexander Street</li> <li>Current Year = 2019</li> <li>Asset Life Expectancy = 11 years</li> <li>Projected Replacement or Upgrade Year = (2019 + 11) = 2030</li> </ul>
Tangible Capital Asset Report Financials	Based on information prepared by Municipal auditors in a Tangible Capital Assets Report, and applied to assets directly or shared amongst assets on a per unit basis (i.e. in the case of linear assets).  Includes Original Value (Starting Balance), Accumulated Amortization, Additions and Betterments, and Ending Value (Net Book Value).	Net Book Value = (Original Value –     Accumulated Amortization +     Additions and Betterments)



Replacement and/or Upgrade Cost	Anticipated total cost of replacement/upgrade/maintenance of an asset (as applicable).  For roads, "Replacement and/or Upgrade Cost" replaced with "Reconstructions / Rehabilitation Cost".  For bridges, "Replacement and/or Upgrade Cost" replaced with "Total Upgrade Cost".	New road, bridge, water asset, wastewater asset
Condition Rating	A scale which identifies the current condition of a given asset.  Roads = Condition Rating based on established Pavement Condition Index (PCI), with Good = PCI > 75, Fair = PCI < 75 and > 50, and Poor = PCI < 50.  Bridges = Condition Rating based on Bridge Condition Index (BCI), with Good = BCI > 70, Fair = BCI < 70 and > 60, and Poor = BCI < 60.  Other assets = Scale using Good, Fair, or Poor rating, based on observations from Municipal Staff and/or consultants.	Alexander Street     PCI = 88     Condition Rating = Good
Current Level of Service	Defined as the level of service required for the asset to be maintained to meet the service requirements of the Municipality and its ratepayers.  Includes consideration of social, political, environmental, and economic outcomes that the Municipality delivers.  The scale is from one (1) to five (5), where one (1) is very low priority and five (5) is very high priority.	High Class Bituminous (HCB) roads with a Municipal Class of 2 (5 = very high priority) Gravel roads with a Municipal Class of 6 with no exit (1 – very low priority)

#### 2.3 Proposed Data Verification and Condition Assessment Policy

In accordance with Section 7 of O.Reg. 588/17, this AMP Report should be re-evaluated at a minimum of every five (5) years; however, it is recommended that this AMP Report be reviewed annually as part of the Municipality's budgeting process, in order to incorporate priority items and actions, and update information relevant to this AMP Report (i.e. current Condition Ratings, new studies, new assets, etc.).

Other studies (and/or updates to studies) to establish qualitative descriptions and technical metrics for core assets and/or all assets should be completed by a municipality every two (2) years, in accordance with Section 5 (2) of O.Reg. 588/17.

Tangible Capital Asset Report information for each asset could be updated annually, based on the results of each year's audited Tangible Capital Assets Report by the Municipality's auditors.

Asset Life Expectancies could be updated following completion of significant maintenance/upgrade activities, in order to note the anticipated extended life of the asset and prolong the Projected Replacement or Upgrade Year.

Replacement and/or Upgrade Costs could be updated as new/more current information becomes available, as applicable.

Condition Ratings could be updated by the Municipality on an as-needed basis, based on municipal review/observations and/or by third-party investigations (i.e. consultant reviews). The ideal case would be to update Condition Ratings annually, and at a minimum every two (2) years.

#### 2.4 Roads

The following information in this section is based on Table 4a – Detailed Summary of Municipal Assets (Roads), which was prepared using information from the Road Needs Study (Greenview, 2019a), 2018 Tangible Capital Assets Report (Baker Tilly, 2019), and information provided by the Municipality. This information is reported in order to meet with the requirements of O.Reg. 588/17. This information can be found directly on Table 2a – 2019 Road Network Summary.



Based on the 2019 Road Needs Study (Greenview, 2019a) and information provided by the Municipality, the Municipality maintains a road network with a total road length of approximately 410.74 km. The respective road surface types and total lengths are as follows:

Road Type	Number of Road Sections	Total Length in Kilometres (km)	No. of Lane Kilometres (km)	Percentage of Tota Road Network
Gravel	166	253.89	507.79	61.81%
HCB	103	30.60	61.20	7.45%
LCB	106	126.25	252.50	30.74%
TOTAL	375	410.74	821.48	100.00%

Road information by Geographic Township is summarized as follows:

Road Type	Grimsthorpe Township	Elzevir Township	Hungerford Township (& Village of Tweed)	Multi-Township Road Sections (Hungerford & Elzevir)	TOTAL		
	Total Length in Kilometres (km)						
Gravel	0.00	55.96	189.58	8.36	253.89		
High Class Bituminous (HCB)	0.00	0.28	30.32	0.00	30.60		
Low Class Bituminous (LCB)	0.26	25.80	100.19	0.00	126.25		
Percentage of Total Road Network	0.06%	19.97%	77.93%	2.03%	100.00%		
TOTAL	0.26	82.04	320.09	8.36	410.74		

Road information by Municipal Road Class is summarized as follows:

Municipal Road Class	Total Length in Kilometres (km)	Percentage of Total Road Network (%)
Class 2	0.58	0.14%
Class 3	16.22	3.95%
Class 4	75.12	18.29%
Class 5	15.89	3.87%
Class 6	302.94	73.75%
TOTAL	410.74	100.00%

Road Information by Municipal Road Class Description is summarized as follows:

Municipal Road Class Description	Total Length in Kilometres (km)	No. of Lane Kilometres (km)	Percentage of Total Road Network (%)	Land Area – Municipality of Tweed (km²)	Road Density (km/km²)
Arterial	0.58	3 1.15 0.14%			0.0012
Major Collector	27.36	54.73	6.66%		0.056
Minor Collector	62.74	125.48	15.27%	975	0.129
Local	319.81	639.61	77.86%		0.656
Partially Maintained	0.26	0.51	0.06%		0.00053
TOTAL	410.74	821.48	100.00%	975	0.421



Road information by Pavement Condition Index (PCI) is summarized as follows:

Road Type	Average PCI	Average Condition Rating	% PCI 75-100	% PCI 50-75	%PCI <50	
		(good / fair / poor)	Good	Fair	Poor	
High Class Bituminous (HCB)	81.25	81.25 Good 17.		9.33%	0.27%	
Low Class Bituminous (LCB)	70.11	Fair	10.13%	17.33%	0.80%	
Gravel	73.01	Fair	22.40%	21.33%	0.53%	
TOTAL	74.45	Fair	50.40%	48.00%	1.60%	

The anticipated total required maintenance cost (gravel roads) and/or replacement cost (LCB/HCB roads) for each road surface type, based on industry standards and information supplied by the Municipality are:

Road Surface Type	Anticipated Total Replacement and/or Maintenance Cost (30-Year
Gravel	\$ 7,500,000
High Class Bituminous (HCB)	\$ 6,566,911
Low Class Bituminous (LCB)	\$ 16,212,229
TOTAL	\$ 30,279,140

In accordance with the requirements of Section 5 (2) of O.Reg. 588/17 regarding the average age of each road surface type, the following average ages of road sections within the Municipality by pavement type are as follows:

Road Surface Type	Average Road Section Age
Gravel	Zero (0) years
High Class Bituminous (HCB)	17 years
Low Class Bituminous (LCB)	9 years

With respect to gravel road sections, maintenance operations are completed annually (and on-going), and therefore the average age of gravel road sections may be described as zero (0) years. The age of various road sections are not interpreted to represent a best practice for managing road assets. It is recommended that the Municipality utilize more quantitative measures for managing road assets, like Pavement Condition Index (PCI) to plan for road asset improvements. Available information on the average age of each road asset category are included on Table 4a.

The above noted summaries of road data are included in the 2019 Road Needs Study (Greenview, 2019a), and has been included here to satisfy the requirements of O.Reg. 588/17. Detailed mapping completed in order to satisfy the requirements of O.Reg. 588/17 with respect to community levels of service (qualitative descriptions), with a focus on the connectivity of roads, pavement types, and current condition rating are included in the 2019 Road Needs Study (Greenview, 2019a). Assumptions and notes related to roads are included on Table 4a — Detailed Summary of Municipal Assets (Roads).

The financial strategy for the upgrade and/or replacement of municipal roads are discussed in Section 5.0 of this report and in Table 5a.

#### 2.5 Bridges and Large Culverts

The following information in this section is based on Table 4b – Detailed Summary of Municipal Assets (Bridges and Large Culverts), which was prepared using information from the 2018 OSIM Bridge Inspection Submission



Asset Management Plan Report Version 1.2 Municipality of Tweed

(Jewell Engineering, 2019), the Municipality's 2018 Tangible Capital Assets Report, and information provided by the Municipality. This information can be found directly on Table 2b – 2019 Bridges and Large Culvert Summary.

Based on the 2018 OSIM Bridge Inspection Submission (Jewell Engineering, 2019), the Municipality maintains a total of fifty-two (52) bridges and/or large culverts (> 3.0 metres) that are inspected every two (2) years, at a minimum. The following details are provided as a summary of the bridge and large culvert assets for the Municipality (Table 4b):

Structure Type	Quantity	Average Age (years)	Replacement and/or Upgrade Cost
Bridges	45	29	\$ 23,804,500
Culverts	7	7	\$ 1,265,000
TOTAL 52		16	\$ 25,069,500

In accordance with the requirements of O.Reg. 588/17, the community levels of service (qualitative descriptions) for the bridges and large culverts in the Municipality include provision for traffic from motor vehicles, heavy transport vehicles, emergency vehicles, pedestrians, and cyclists. With respect to technical levels of service (technical metrics), the following is a summary of the % Load Restrictions and % Dimensional Restrictions of the Municipality's bridges and large culvert, as noted on Table 2b.

Structure Type	Quantity	% Loading Restrictions	% Dimensional Restriction
Bridges	45	44%	58%
Culverts	7	0%	14%
TOTAL	52	38%	52%

Additional details on the Municipality's bridges and large culverts can be found in the 2018 OSIM Bridge Inspection Submission (Jewell Engineering, 2018) and on Table 4b.

Assumptions and notes related to bridges and large culverts are included on Table 4b – Detailed Summary of Municipal Assets (Bridges & Large Culverts).

The financial strategy for the upgrade and/or replacement of Municipal bridges and large culverts is discussed in Section 5.0 of this report and in Table 5b.

#### 2.6 Water Supply Services (Updated August 2021)

The following information in this section is based on Table 4c – Detailed Summary of Municipal Assets (Water Supply Services), which was prepared using information from applicable water supply services-related documentation (as included as appendices in the Water Asset Study, Greenview, 2019b), the Municipality's 2018 Tangible Capital Assets Report, and information provided by the Municipality. This information can be found directly on Table 2c - 2019 Water Supply Services Summary. As part of this AMP Report Version 1.2, updates to Asset IDs WS21-67 and WS21-88 were applied, which corresponding changes to the following data:



Asset Description & Class		sset Description & Class Construction Material Quantity		Units	Average Age (years)	Replacement and/o Maintenance Cost	
Building	Distribution		1	#	22	\$ 1,500,000	
Building	Treatment	and property to the second	1	#	21	\$ 1,000,000	
Equipment	Distribution		5	#	7	\$ 2,085,000	
Water Main	Distribution	Cast Iron	7,570	m	82	\$ 7,257,190	
Water Main	Distribution	PVC	8,002	m	17	\$ 6,801,887	
Equipment	Hydrant		97	#	20	\$ 970,000	
Equipment	Treatment	4.74	8	#	14	\$ 275,000	
TOTAL	B				33	\$ 19,889,077	

With respect to technical levels of service (technical metrics), the following is a summary of the requirements of O.Reg. 588/17 for water supply services assets:

Percentage of Percentage of Properties Properties Where Fire Municipal Water System Available		No. of Connection Days per Year where a Boil Water Advisory Notice is in Place Compared to the Total Number of Properties Connected to the Municipal Water System	No. of Connection-Days per Year Due to Water Main Breaks Compared to the Total Number of Properties Connected to the Municipal Water System
= (730 / 4,695)	= (730 / 4,695)	= (730 x 2) / 730	= (10 x 2) / 730
= 15.5%	= 15.5%	= 2	= 0.027

Detailed mapping completed in order to satisfy the requirements of O.Reg. 588/17 with respect to community levels of service (qualitative descriptions), with a focus on the areas of the Municipality that are connected to the municipal water system and have fire flow, are included in the Water Asset Study (Greenview, 2019b). Assumptions and notes related to water supply services are included on Table 4c – Detailed Summary of Municipal Assets (Water Supply Services).

The financial strategy for the upgrade and/or replacement of the Municipality's water supply services assets are discussed in Section 5.0 of this report and in Table 5c.

#### 2.7 Wastewater Services

The following information in this section is based on Table 4d – Detailed Summary of Municipal Assets (Wastewater Services), which was prepared using information from applicable wastewater services-related documentation (as included as appendices in the Wastewater Asset Study, Greenview, 2019c), the Municipality's 2018 Tangible Capital Assets Report, and information provided by the Municipality. This information can be found directly on Table 2d – 2019 Wastewater Services Summary.



Asset Description and Class		set Description and Class Sewer Type Quantity		Units	Average Age (years)	Replacement and/o Maintenance Cost	
Facility	Distribution		2	#	44	\$ 450,000	
Equipment	Distribution		5	#	5	\$ 98,000	
Equipment	Treatment		3	#	15	\$ 155,000	
Land	Treatment		2	#	44	\$ 200,000	
Sewer	Distribution	PVC	6,982	m	16	\$ 3,490,965	
Sewer	Distribution	Asbestos Cement	6,146	m	81	\$ 3,072,868	
Sewer	Distribution	Forcemain	1,570	m	44	\$ 785,000	
TOTAL					45	\$ 8,251,833	

With respect to technical levels of service (technical metrics), the following is a summary of the requirements of O.Reg. 588/17 for wastewater services assets:

Percentage of Properties Connected to the Municipal Wastewater System	No. of Events per Year Where Combined Sewer Flow in the Municipal Wastewater System Exceeds System Capacity Compared to the Total Number of Properties Connected to the Municipal Wastewater System	No. of Connection-Days per Year Due to Wastewater Backups Compared to the Total Number of Properties Connected to the Municipal Wastewater System	No. of Effluent Violations per Year Due to Wastewater Discharge Compared to the Total Number of Properties Connected to the Municipal Wastewater System
= (730 / 4,695)		No connection-days occur	= (3 / 730)
= 15.5%	The municipal wastewater system does not have combined sewers.	when a wastewater service issue arises, as there are no interruptions in service as bypassing and/or discharges are undertaken to avoid backups.	= 0.004

Detailed mapping (and related information) completed in order to satisfy the requirements of O.Reg. 588/17 with respect to community levels of service (qualitative descriptions), with a focus on the areas of the Municipality that are connected to the municipal wastewater system, are included in the Wastewater Asset Study (Greenview, 2019c). Assumptions and notes related to wastewater services are included on Table 4d – Detailed Summary of Municipal Assets (Wastewater Services).

The financial strategy for the upgrade and/or replacement of the Municipality's wastewater services assets are discussed in Section 5.0 of this report and in Table 5d.

#### 2.8 Stormwater Assets (New June 2021)

The following information in this section is based on Table 4e – Detailed Summary of Municipal Assets (Stormwater Assets), which was prepared using information from applicable stormwater services-related documentation (as included as appendices in the Stormwater Asset Study, Greenview, 2021a), the Municipality's 2018 Tangible Capital Assets Report, and information provided by the Municipality. This information can be found directly on Table 2e – 2020 Stormwater Asset Summary.

Based on information presented in the Stormwater Asset Study (Greenview, 2021a), seven (7) catchment areas were identified within the Village of Tweed, and five (5) catchment areas in the Municipality's hamlets, including Actinolite, Marlbank, Queensborough, Stoco, and Thomasburg. The catchment area in Actinolite was not reviewed in detail, as it is understood that there are no known stormwater assets located within the hamlet.



Asset Description	Number of Catchment Areas	Total Hectares (ha)	Total Inlet Structures (#)	Total Outlet Structures (#)	Total Properties At Risk to Flooding to 100-year Storm (#)	Total Systems Not Resilient to a 5- year Storm (#)	Average Age (years)	Replacement and/or Maintenance Cost
Catchment Area (Small)	7	8	20	6	61	0	25	\$ 160,000
Catchment Area (Medium)	2	12	49	2	5	1	32	\$ 490,000
Catchment Area (Large)	2	110	226	3	0	1	37	\$ 1,960,000
Catchment Area (Multi)	1	30	61	individual outlets	10	-	37	\$ 610,000
TOTAL	12	160	356	11	76	2	35	\$ 3,220,000

Detailed mapping (and related information) completed in order to satisfy the requirements of O.Reg. 588/17 with respect to community levels of service (qualitative descriptions), with a focus on stormwater catchment areas of the Municipality, are included in the Stormwater Asset Study (Greenview, 2021a). Assumptions and notes related to stormwater assets are included on Table 4e – Detailed Summary of Municipal Assets (Stormwater Assets).

With the exception of the stormwater assets in the hamlet of Stoco (approximately 10 years old), the exact ages of stormwater assets within the Municipality are not well defined, as their various installation dates are understood to predate current senior staff's experience at the Municipality. For this reason, a review of the known asset ages for wastewater assets in the vicinity of the stormwater catchment areas was completed, with estimated installation dates ranges for stormwater-related assets established as likely between 1983 and 1988. If additional information on the various ages of stormwater assets within the Municipality becomes available, the Year in Service for assets within the catchment areas could be updated accordingly in future.

With respect to technical levels of service (technical metrics), the following is a summary of the requirements of O.Reg. 588/17 for stormwater assets:

Percentage of Properties in Municipality that are Resilient to 100-year Storm	Percentage of Municipal Stormwater Management System Resilient to a 5-year Storm
= (4,870 Total Properties in Municipality) - (76 Properties At Risk to 100-year Storm) + (4,870 Total Properties in Municipality) x 100%	= (Total Number of Inlet Structures – Inlet Structures in Tweed East) + (Total Number of Inlet Structures) x 100%
= 98.44%	92.42%

The financial strategy for the upgrade and/or replacement of the Municipality's stormwater assets are discussed in Section 5.0 of this report and in Table 5e.



#### 3.0 Current Levels of Service (Updated August 2021)

For the purposes of this AMP Report, level of service is defined as the level of service required for an asset to be maintained to meet the service requirements of the Municipality and its ratepayers. Determination of current level of service includes consideration of social, political, environmental, and economic outcomes that the Municipality delivers. For the purposes of Version 1.2 AMP Report and associated tables, the scale is from one (1) to five (5), where one (1) is very low priority and five (5) is very high priority.

Generally, the current and desired level of service for service issues for each asset category are understood to be relatively consistent. At this time, it is understood that the Municipality does not have the resources (i.e. budget) to increase the level of service for its assets in the short-term, and it is the Municipality's objective to maintain their existing asset base in the best and most effective way possible, given their existing resources. Current levels of service as established by the Municipality as part of this Version 1.2 AMP Report are included in Tables 4a to 4e in columns labeled "Current Level of Service".

As part of any re-evaluation of this AMP Report (as described in Section 2.3 of this AMP Report), levels of service should be concurrently re-evaluated.

The following are descriptions of the current level of service and performance measures review for each of the asset categories included in this Version 1.2 AMP Report.

#### 3.1 Roads

Gravel roads are currently understood to have the following service issues: grading, resurfacing, calcium treatment, brushing, ditching, winter plowing, winter sanding/salting, washout repairs, and shoulder maintenance.

Similarly, paved roads (including HCB and LCB) are currently understood to have the following service issues: sweeping, patching/potholes, shoulder maintenance, resurfacing/sealant, brushing, winter plowing, winter sanding/salting, ditching, and washout repairs.

Current levels of service for the Municipality's roads were reported as part of this AMP Report in Table 4a, and were dependent on pavement type (HCB, LCB, or gravel) and the Municipal Classes identified in the Municipality's *Level of Service Policy – Minimum Maintenance Standards* (Municipality of Tweed, 2018) and in general accordance with O.Reg. 239/02 – Minimum Maintenance Standards for Municipal Highways.

For the purposes of this AMP Report, the following Levels or Service have been designated to specific road sections as follows:

Municipal Road Class	Level of Service (1 = very low, 5 = very high)
Road Class 2 (Arterial)	5
Road Class 3 (Major Collector)	4
Road Class 4 (Minor Collector)	3
Road Class 5 (Local)	2
Road Class 6 (Local or Partially-Maintained)	1

In a general sense, HCB and LCB roads within the Municipality were determined to have the highest level of service (generally values of 5, 4, or 3), whereas gravel roads were determined to have lower levels of service (generally between 2 and 1). The lowest levels of service for road sections in the Municipality were determined to be gravel road sections that do not connect with other roads (i.e. dead-ends).

Table 4a identifies all road sections evaluated as part of this AMP Report and their respective Current Levels of Service.



#### 3.2 Bridges and Large Culverts

Bridges and large culverts are currently understood to have the following service issues: sweeping, blockages, damage (i.e. guide rails), supports (bridges only), winter plowing, winter sanding/salting, surface, and failure. Service issues should be noted in biennial (every 2 years) OSIM reports, as prepared by a Professional Engineer.

Levels of Service for each bridge and large culvert within the Municipality have been reported based on the road on which the bridge or large culvert is located and the Level of Service for that road section, as noted above in Section 3.1 of this AMP Report.

Table 4b identifies all bridges and large culverts evaluated as part of this AMP Report and their respective Current Levels of Service.

#### 3.3 Water Supply Services

All water supply services assets connected to the Municipality's water services system are considered critical to public health and safety and any issues, whether minor or major, should be addressed equally. This applies to assets related to the process or chemical feed system, mechanical and electrical systems, wells, water mains, hydrants, service connections, pumps, valves and related equipment.

Levels of Service for all elements of the Municipality's water supply services are understood to be very high (Level of Service = 5), given their importance to public health and safety (i.e. safe drinking water, fire services, etc.).

Table 4c identifies all water supply services assets evaluated as part of this AMP Report and their respective Current Levels of Service.

#### 3.4 Wastewater Services

All wastewater services assets connected to the Municipality's wastewater services are considered critical to public health and safety and any issues, whether minor or major, should be addressed equally. This applies to assets related to the sanitary sewers, process and chemical feed system, mechanical and electrical systems, service connections, pumps, valves and related equipment.

Levels of Service for all elements of the Municipality's wastewater services are understood to be very high (Level of Service = 5), given their importance to public health and safety (i.e. protection from contamination, safe drinking water, etc.).

Table 4d identifies all wastewater services assets evaluated as part of this AMP Report and their respective Current Levels of Service.

#### 3.5 Stormwater Assets (New June 2021)

Stormwater assets connected to the Municipality's stormwater catchment areas were reviewed by the Municipality as part of the asset assessment activities, and stormwater assets in catchment areas located within the Village of Tweed were generally designated with higher Levels of Service than stormwater assets in catchment areas associated with the hamlets located in the Municipality (as stormwater assets in the Municipality's hamlets were generally less complex than those located within the Village of Tweed). This applies to assets related to catchbasins, piping, headwalls, outlets, and related assets.

Levels of Service for elements of the Municipality's stormwater assets within the Village of Tweed were understood to be medium to very high (Levels of Service = 3 to 5), while within the Municipality's hamlets they were understood to be low (Level of Service = 2).

Table 4e identifies all stormwater assets evaluated as part of this AMP Report and their respective Current Levels of Service.



#### 4.0 Procurement and Options Analysis

The following sections discuss procurement methods and options analysis for the Municipality's assets reviewed as part of this AMP Report.

#### 4.1 Procurement Methods

Procurement of new or replacement assets should be completed in accordance with any applicable Municipality procurement bylaws.

Due to the rural nature of many parts of the Municipality and the distance of the Municipality from large urban centres, challenges with regards to procurement of services or products are anticipated, as there are generally fewer available service providers in the vicinity of the Municipality than in more densely populated areas. Depending on the circumstances, the rural nature of the Municipality can have positive and negative impacts on the cost of procurement of products and services. In cases where local service providers are available, the cost for services are generally expected to be less than city prices; however, where no local service providers are available, then the cost for services are generally expected to be elevated as distance-related factors emerge (i.e. elevated mobilization costs, etc.).

Multi-municipal cooperation in new or replacement projects for assets and services could be considered as part of the Municipality's procurement methods. Multi-municipal cooperation as part of procurement methods can have a positive effect from an economies of scale perspective, with the potential of financial benefits to all parties involved.

If any amendments to the Municipality's procurement bylaw are required to enter into multi-municipal agreements or partnerships, they should be considered by the Municipality on a per project basis.

As part of the budgeting of future projects, the Municipality should consider the design-build-finance-maintain model for budgeting purposes (i.e. AFP model), in order to apply due consideration to the total lifecycle costs of asset-related projects.

#### 4.2 Options Analysis Review (Updated June 2021)

Options analysis could be considered when the Municipality is reviewing maintenance, upgrade, or replacement of assets. This can help the Municipality to provide the needed level of service for its assets to its ratepayers.

Options analysis generally involves the following process of establishing project alternatives:

- Option identification.
- 2. Feasibility analysis.
- 3. Option selection.

Financial assessment and projections for each asset category are included Tables 5a to 5e of this AMP Report, and discussed in Section 5.0. Financial projections were developed in straight-line amortizations. If necessary, for any future asset replacement activities, more detailed reviews of replacement costs could be developed, and this AMP Report should be updated accordingly with any new or updated information.

Direct benefits and costs for an asset upgrade or replacement project should be considered on a per asset basis as part of an options analysis process, with specific consideration of the following (as may be applicable):

- Efficiencies and network effects.
  - Ontario Regulation [O.Reg.] 397/11 Energy Conservation and Demand Management Plans.
  - Labour and vehicle operating cost savings.
  - Multi-municipal cooperation.
  - Performance improvements.



- Investment scheduling and waste minimization.
  - Delay projects that could be impacted by any expansion activities (i.e. roads).
  - Coordinate multiple asset upgrades/replacements (i.e. roads, water supply services, wastewater services, stormwater assets).
- Health and Safety.
  - Accident reduction.
  - Property damage reduction.
  - Injury reduction.
- Environmental Impacts.
  - Greenhouse gas emissions.
  - Nutrient loading.
  - Groundwater and surface water impacts.
  - Drainage impacts/improvements.
  - Climate change.

Indirect benefits and costs for an asset upgrade or replacement project should be considered on a per asset basis, with specific consideration of the following (as may be applicable):

- Municipal well-being and health.
- Amenity values.
  - Public facilities (i.e. washrooms, parks, etc.).
- Culturally/historically significant assets.
  - Historical buildings.
  - Parks and land improvements.
- Municipal image.

As this AMP Report is designed to be an asset planning tool for the Municipality, an assessment of the risks associated with all potential asset maintenance, upgrade, or replacement should be considered using an approach that allows for comparative analysis of the options available. Risks associated with each option could be based on quantitative data (if available). In instances when quantitative data is not available as part of the comparative analysis review, qualitative measures could be utilized with the intent of determining the probability of the occurrence of risk events.

Due to the fact that the Municipality is a small, rural municipality with limited resources, additional study focused on quantitative data gathering with respect to specific risk assessments could be reviewed in future as part of updates to this AMP Report, if deemed valuable by the Municipality (Section 5.5 of this AMP Report).

For any review of this AMP Report, any opportunities to save resources by coordinating solutions to multiple problems concurrently should be explored. Specifically, and as part of any decision-making process, the following opportunities should be considered:

- 1. Multi-municipal cooperation and contract negotiation.
- 2. Joint service boards.
- 3. Shared and/or uploading of services to the upper tier (i.e. County of Hastings).



#### 5.0 Financial Strategy

The following sections discuss the financial strategy for the Municipality's assets reviewed as part of this AMP Report.

#### 5.1 Summary and Definitions (Updated August 2021)

The financial strategy for the Municipality was developed with the assistance of Municipal staff and Greenview, and is considered the critical component of this AMP Report. The financial strategy is designed to employ basic fundamentals and assumptions, such that the Municipality could amend and/or update this AMP Report in future years as information and data becomes available.

Tables 5a to 5e – Financial Assessment and Projections describe the core municipal assets included in this AMP Report by asset category including:

- Table 5a Financial Assessment and Projections Roads.
- Table 5b Financial Assessment and Projections Bridges & Large Culverts.
- Table 5c Financial Assessment and Projections Water Supply Services (Updated August 2021).
- Table 5d Financial Assessment and Projections Wastewater Services.
- Table 5e Financial Assessment and Projections Stormwater Assets (New June 2021).

Based on the scope of this AMP Report, Tables 5a to 5e account for an all-inclusive review of the replacement (or upgrade) costs for each core asset, and consideration has been given by the Municipality relative to non-infrastructure solutions, maintenance activities, renewal/rehabilitation activities, replacement activities, disposal activities, and expansion activities associated with the replacement costs identified.

A practical and detailed review was completed by the Municipality and Greenview in the determination of replacement costs, including, but not limited to, actual expenditures on similar assets and/or research completed by the Municipality or Greenview on actual costs of replacement within the last two (2) to three (3) years (where possible).

A summary of the financial assessment and projections of Tables 5a to 5e is included in Table 3a – General Summary of Municipal Assets. As noted in Section 2.0 of this AMP Report, Tables 3b (Municipal Reserves and Allocation Summary) and 3c (Detailed Municipal Reserves Allocation Calculations) were created in an effort to correlate current Municipality reserves that would apply to each asset category. Current reserves were divided into reserves that are applicable to this AMP Report and to reserves that are not applicable to this AMP Report. Reserves that are applicable to this AMP Report, whether directly to specific assets categories, operating departments, or specific assets, or generally to asset categories, were used to reduce the Projected Contributions to Reserves in Table 5a to 5e. As noted in Section 2.0, the Municipality should complete a detailed review on their current reserve funds to determine if any other reserve funds (or portions of reserve funds) could be applied against any core asset categories in this AMP Report.

Tables 5a to 5e incorporate pertinent information required from Tables 4a to 4e, as well as detailing the proposed annual contributions to reserves required to upgrade/replace each municipal asset over its remaining useful life. In the event that an asset has already reached its projected replacement or upgrade year, then the proposed annual contribution to reserves is determined to be equal to the replacement cost of the asset; however, if the asset has not reached the projected replacement or upgrade year, then the value included for Year 1 is equal to the amount of available reserves calculated for the given asset, and the cost of upgrade/replacement (replacement cost) is divided over the remaining useful life years.

Proposed annual contributions to reserves are determined with focus on the five (5) and ten (10) year planning horizon, and with consideration of the thirty (30) year and total life expectancy planning perspective. The proposed annual contributions to reserves (for each year) are the recommended total monies to be saved per year by the Municipality in order to replace/upgrade each asset at the end of its useful life.



For comparison purposes, the estimated borrowing cost is calculated based on the cost for the Municipality to borrow the required monies from Infrastructure Ontario to upgrade/replace each asset, consistent with recent lending rates. Lending rates can be updated on Tables 5a to 5e at any time, to reflect the most recent rates available when this AMP Report is under review by the Municipality. The term of the loan is assumed to be generally equal to asset life expectancy, rounded up to the nearest five (5) years, to a maximum of a thirty (30) year lending term. Additionally, the difference in cost to the Municipality between borrowing or saving the required funds to upgrade/replace each asset is calculated and identified as difference (borrowing — savings). This calculation is designed to illustrate the monetary benefits to the Municipality of saving money (as part of their reserves) in advance of asset upgrade/replacement, in comparison to the high costs of borrowing; however, in some cases, borrowing money to upgrade and/or replace a municipal asset may be the appropriate action (as may be applicable).

The proposed annual contributions to reserves and associated replacement costs assume the Municipality will need to obtain all funds required to upgrade/replace each asset without the assistance of Federal or Provincial funding, grants, or any other assistance.

Assumptions and notes associated with Tables 5a to 5e are included on each individual table.

#### 5.2 Integration with Municipal Budgets

The financial strategy was developed with a cost-based approach, using real-life upgrade/replacement costs for assets, as currently understood by the Municipality. This AMP Report is not directly integrated with municipal budgets and is designed to be an independent, third-party review of the actual assets owned and managed by the Municipality.

This AMP Report should be reviewed, updated, and utilized with consideration of future municipal budgets, existing municipal reserves, Financial Information Returns (FIR), audited Financial Reports, audited Tangible Capital Asset Reports, and any other pertinent financial or planning documents of the Municipality.

On an annual basis, or at least every two (2) years, it is recommended that any new municipal assets not represented in this AMP Report be included for future planning purposes.

#### 5.3 Maintenance Versus Upgrade/Replacement of Assets

As the upgrade and/or replacement costs of each asset are understood to be generally costly to the Municipality, particularly in years where multiple assets require at least some level of upgrade or replacement, maintenance activities on assets should be strongly considered as a viable alternative.

Maintenance activities can be used to prolong the asset life expectancy, improve the condition rating of the asset, and in some cases revise the year in service of the asset where maintenance activities improved the condition of the asset to a like-new state.

The benefits of an appropriate maintenance schedule for municipal assets include, but may not be limited to, the following:

- Increasing available funds to be used in other maintenance, upgrades, or replacement of assets.
- Prolonging asset life expectancies beyond accounting-based estimates/pre-determined values.
- Allowing for additional years for the Municipality to save/budget for replacement assets.

#### 5.4 Assumptions on Future Changes in Population and Economic Activity

Given the small, rural nature of the Municipality, significant changes in population and economic activity are not expected within the next 10-year and 30-year planning horizons. Conditions are anticipated to remain generally consistent with current Statistics Canada data (Table 1). Per Statistics Canada, the population percent change



in the Municipality between 2011 to 2016 was -0.2%, which was interpreted to represent a generally steady-state for the Municipality's population.

Based on the above, the following is interpreted to be pertinent to lifecycle activities for municipal assets:

- Maintaining levels of service at current levels for municipal assets is interpreted to be possible, based on the current tax base.
- Lifecycle activities for specific core municipal assets should be considered on a case-by-case basis by Municipal Staff and/or consultants, but in general, lifecycle activities for similar assets (i.e. roads, bridges, etc.) should be conducted in a consistent manner, and be based on appropriate studies/reviews and technical metrics.
- As part of the determination of lifecycle activities that differ from replacement/upgrade (or similar), the Municipality should also consider if risk elements are subsequently increased as it pertains to level of service on a case-by-case basis for any municipal asset.
- 4. Decision-making processes with respect to level of service and risk should be completed with consideration of the lowest cost alternative, whilst maintaining the desired level of service for its ratepayers over the short and long-term planning horizons.

#### 5.5 Detailed Risk Assessments and Asset Management Planning Activities

A detailed risk assessment for the core assets of the Municipality was not part of the scope of the AMP Report (Version 1.2). However, in future it may be desirable for the Municipality to consider analysing their core assets from a risk management perspective. Risk may be defined in various way; however, the following two (2) examples of the definition of risk are interpreted to be useful for establishing context:

- 1. Federation of Canadian Municipalities (FCM) Definition:
  - The product of the likelihood and consequence of an undesirable event or circumstance (i.e. Risk = (Likelihood X Consequence)).
- 2. ISO 55000:2014 Asset Management Definition:
  - The effect of uncertainty on objectives (or result to be achieved). An effect is a deviation from the expected – either positive or negative.

Risk management involves a focus on identifying and assessing risk and determining methods to mitigate the risk from multiple potential risk elements: Examples of risk elements include:

- 1. Deteriorating or aging assets.
- 2. Threats to public health and safety.
- 3. Natural disasters.
- 4. Climate change.
- 5. Downgrading Level of Service of assets.

As part of risk assessment activities, there are many tools that can be utilized including the Bowtie model, Risk Matrix model, and Decision Tree model, among others. The appropriate model to utilize should be examined at the time of implementation of detailed risk assessments for municipal assets.

#### 5.6 Determination of Priority Assets for Replacement/Upgrade (Updated June 2021)

The determination of priority assets for replacement or upgrade should be considered based upon multiple factors, rather than on a singular element (i.e. Projected Replacement or Upgrade Year). It is recommended that the determination of a priority asset for replacement or upgrade should, at a minimum, consider the following aspects, as indicated in Tables 4a to 4e:



- 1. Year in Service.
- 2. Asset Life Expectancy.
- 3. Projected Replacement or Upgrade Year.
- 4. Condition Rating (or PCI/BCI, in case of road or bridge assets).
- 5. Current Level of Service.

Determination of priority assets for replacement or upgrade should also consider available municipal budget monies, available municipal reserves, or any Federal or Provincial funding or grants available at that time. Any special projects, as determined by the Municipality prior to the development of this AMP Report, should also be considered for priority asset status (as may be applicable).



#### 6.0 Priorities and Recommendations (Updated August 2021)

Based on the data presented in Tables 4a to 4e, and Tables 5a to 5e, the following is a summary of the priority assets, by category, that should be considered for replacement and/or upgrade (or additional review) by the Municipality as part of this AMP Report (Version 1.2).

#### 6.1 Roads

Based on the details presented in Table 4a – Detailed Summary of Municipal Assets (Roads) and related field investigations of the Municipality's roads in the 2019 Road Needs Study (Greenview, 2019a), the following priority road sections are recommended to be investigated further as part of future road reconstruction/rehabilitation, and/or maintenance opportunities. The priority road sections for further investigation were determined by the following procedure:

- 1. Sorting the data for all road sections by pavement type, based on the PCI (lowest to highest).
- 2. Sorting the top ten (10) road sections with the lowest PCI by Current Level of Service (highest level of service = 5, lowest level of service = 1), and then by PCI value.

The top five (5) road sections with the lowest PCI values were then selected and included the sections below. In cases where road sections in the top 10 had identical PCI values and Current Levels of Service, then they were included, in order to not preferentially select road sections based on alphabetical order. For this reason, both Sections 6.1.1 (HCB Road Sections) and 6.1.3 (Gravel Road Section) have six (6) road sections identified below, and Section 6.1.2 (LCB Road Sections) has seven (7) road sections identified in their respective table.

It is recommended that the Municipality consider population density and traffic volumes (i.e. established through traffic studies) in order to further review the above noted list of potential priority road sections for reconstruction, rehabilitation and/or maintenance.

Priority road assets recommended for further review are summarized in Table 6a of this AMP Report.

#### 6.1.1 HCB Road Sections

The following HCB road sections have been identified as assets that should be considered for additional review as part of asset management planning initiatives in the Municipality. Six (6) HCB road sections are included below:

Asset ID	Asset Name	Detailed Asset Desc.	Road Location From	Road Location To	Section Length (m)	Asset Life Expectancy	PCI (0- 100)	Current Level of Service	Recon. / Rehab. Cost
R19-194	Marlbank Road	НСВ	Bethel Road	Mulroney Lane	703	5	57	4	\$ 158,619
R19-200	Marlbank Road	НСВ	East Hungerford Road	St. Edmunds Road	397	5	57	4	\$ 88,123
R19-205	Marlbank Road	HCB	Mulroney Lane	Kenner Court	886	6	60	4	\$ 190,163
R19-286	Quinns Lane	НСВ	Victoria Street	Colborne Street	95	4	46	2	\$ 13,943
R19-149	James Street North	НСВ	Jamieson Street	Hannah Street	100	5	56	2	\$ 20,271
R19-268	Pomeroy Court	НСВ	College Street	End	52	5	56	2	\$ 5,915



#### 6.1.2 LCB Road Sections

The following LCB road sections have been identified as assets that should be considered for additional review as part of asset management planning initiatives in the Municipality. Seven (7) LCB road sections are included below:

Asset ID	Asset Name	Detailed Asset Desc.	Road Location From	Road Location To	Section Length (m)	Asset Life Expectancy	PCI (0- 100)	Current Level of Service	Recon. / Rehab. Cost
R19-245	Napanee Road	LCB	Moneymore Road	Municipal Boundary	2,015	4	41	3	\$ 270,804
R19-244	Napanee Road	LCB	Marlbank Road	Moneymore Road	561	4	44	3	\$ 73,231
R19-334	Store Street	LCB	Hungerford Street	Highway 37	333	5	50	2	\$ 38,778
R19-313	Sexsmith Road	LCB	Highway 7	End	264	4	49	1	\$ 37,950
R19-47	Charles Road	LCB	Charles Court	End	470	5	50	1	\$ 59,083
R19-296	Rapids Road	LCB	Martin Road	Marrisett Road	1,498	5	50	1	\$ 186,000
R19-342	Sulphide Road	LCB	Potter Settlement Road	Peter Street	1,850	5	50	1	\$ 260,231

#### 6.1.3 Gravel Road Sections

The following gravel road sections have been identified as assets that should be considered for additional review as part of asset management planning initiatives in the Municipality. Six (6) gravel road sections are included below:

Asset ID	Asset Name	Detailed Asset Desc.	Road Location From	Road Location To	Section Length (m)	Asset Life Expectancy	PCI (0- 100)	Current Level of Service	Recon. / Rehab. Cost
R19-160	Kaladar Street	Gravel	Bridgewater Road	Highway 37	215	n/a	52	2	To be determined
R19-150	James Street South	Gravel	George Street	River Street	134	n/a	55	2	To be determined
R19-266	Peterson Road	Gravel	Highway 7	End	560	n/a	44	1	To be determined
R19-14	Bethel Road	Gravel	Mulroney Lane	End	80	n/a	48	1	To be determined
R19-80	Deroche Road	Gravel	Conchie Road	Deroche Lane	1,422	n/a	50	1	To be determined
R19-175	Lingham Lake Road	Gravel	Boundary	End	6,500	n/a	50	1	To be determined

#### 6.2 Bridges and Large Culverts

Based on a review of the 2018 OSIM Bridge Inspection Submission (Jewell Engineering, 2019), specific repair and rehabilitation requirements were noted for the Municipality's bridges and large culverts. Details regarding



each bridge or large culvert are included on Table 4b – Detailed Summary of Municipal Assets (Bridges and Large Culverts).

Based on the details presented in Table 4b – Detailed Summary of Municipal Assets (Bridges and Large Culverts), and reported in the 2018 OSIM Bridge Inspection Submission (Jewell Engineering, 2019), the following priority bridges and large culverts are recommended to be investigated further as part of future repairs, reconstruction/rehabilitation, replacement and/or maintenance opportunities. The priority bridges and large culverts for further investigation were determined by the following procedure:

- Sorting the data for all bridges and large culverts based on the Bridge Condition Index (BCI) from lowest BCI to highest BCI.
- 2. Sorting the top ten (10) bridges and large culverts with the lowest BCI by Current Level of Service (highest level of service = 5, lowest level of service = 1), and then by BCI value.

The top five (5) bridges and large culverts recommended for further review based on the above-noted process are as follows:

Asset ID	Asset Name	Detailed Asset Desc.	Asset Life Expectancy Remaining (years)	Condition Rating	BCI (0-100)	Current Level of Service	Replacement and/or Upgrade Cost
BC19-39	Reynolds Culvert (Bridge #38)	Culvert	10	Poor	44.76	3	\$510,000
BC19-41	Rocky Alter Bridge (Bridge #12)	Bridge	5	Poor	21.13	1	\$855,000
BC19-26	Lost Channel Bridge (Bridge #6)	Bridge	5	Poor	23.06	1	\$2,158,000
BC19-13	East Red Bridge (Bridge #30)	Bridge	5	Poor	27.83	1	\$495,000
BC19-05	Catons Bridge North Structure (Bridge #8)	Bridge	5	Poor	28.42	1	\$1,555,000

Given that the Catons Bridge South Structure (Bridge #7) also has a similarly poor BCI rating as its North Structure counterpart (Bridge #8), it is recommended that it be included in any further investigations for repairs, reconstruction/rehabilitation, or replacement activities as they are located in approximately the same location. Similarly, the West Red Bridge (Bridge #31) reportedly has a poor condition rating and a BCI of 50.93, similar to its East Red Bridge counterpart, so consideration of further investigations of the West Red Bridge concurrently with investigations at the East Red Bridge are recommended. Details regarding the West Red Bridge and the Catons Bridge South Structure are as follows:

Asset ID	Asset Name	Detailed Asset Desc.	Asset Life Expectancy Remaining (years)	Condition Rating	BCI (0-100)	Current Level of Service	Replacement and/or Upgrade Cost
BC19-06	Catons Bridge South Structure (Bridge #7)	Bridge	5	Poor	31.17	1	\$ 1,555,000
BC19-52	West Red Bridge (Bridge #31)	Bridge	5	Poor	50.93	1	\$ 815,000

Priority bridge and large culvert assets recommended for further review are summarized in Table 6b of this AMP Report.

#### 6.3 Water Supply Services (Updated August 2021)

Based on the details presented in Table 4c - Detailed Summary of Municipal Assets (Water Supply Services),



and reported in the Water Asset Study (Greenview, 2019b), the following priority water supply services assets are recommended to be investigated further as part of future repairs, reconstruction/rehabilitation, replacement and/or maintenance opportunities. The priority water supply services assets for further investigation were determined by the following procedure:

 Sorting the data for all water supply services assets based on the condition rating, from lowest (poor) to highest (good).

Given that the current level of service for all water supply services assets were understood to have the highest level of service (Level of Service = 5), further sorting by current level of service was not deemed to be significant, and an alternative method of priority sorting was required.

The following alternative priority sorting methodology was utilised:

1. Given that water supply services assets that were identified as having a "poor" condition rating were dominantly Fire Hydrants, all Fire Hydrant assets with a "poor" condition rating were then sorted by Year in Service (or Last Upgrade Year). The five (5) oldest Fire Hydrants with a "poor" condition rating were identified as follows:

Asset ID	Asset Name	Detailed Asset Desc.	Asset Class	Year in Service	Condition Rating	Additional Information	Replacement and/or Upgrade Cost
WS19-187	Fire Hydrant (No. 82)	Equipment	Hydrant	1931	Poor	Leaking from operating nut. Formerly #429.	\$ 10,000
WS19-199	Fire Hydrant (No. 94)	Equipment	Hydrant	1949	Poor	Leaking from operating nut. Caps need gaskets. To be replaced. Formerly #432.	\$ 10,000
WS19-198	Fire Hydrant (No. 93)	Equipment	Hydrant	1950	Poor	To be replaced. Formerly #433.	\$ 10,000
WS19-185	Fire Hydrant (No. 80)	Equipment	Hydrant	1953	Poor	To be replaced. Formerly #406.	\$ 10,000
WS19-175	Fire Hydrant (No. 70)	Equipment	Hydrant	1969	Poor	Caps need new gaskets. Formerly #415.	\$ 10,000

The replacement and/or upgrade costs of approximately \$10,000 per hydrant represent the cost to replace and install a full, new hydrant; however, based on observations of deficiencies in 2019 (i.e. during the fire flow testing completed by Lakeshore Hydrant Services Inc.), only two (2) of the five (5) hydrants noted above are understood to require replacement. It is recommended that as many of the Fire Hydrants identified on Table 4c as requiring maintenance only (not replacement) be considered as part of municipal budgeting in the short-term planning period. Ultimately, thirty-three (33) Fire Hydrants in the Village of Tweed were identified as being in "poor" condition, and require either maintenance or replacement (Table 4c).

As it pertains to other water supply services assets (excluding Fire Hydrants), the following sorting methodology was conducted in order to determine water supply services assets for further investigation:

1. Sorting the data for all water supply services assets based on the condition rating, from lowest (poor) to highest (good), followed by sorting on Year in Service (or Last Upgrade Year).

The sorting of water supply services assets (excluding Fire Hydrants) by this methodology resulted in an asset set of Water Mains of similar age and construction material, with the exception of WS21-67 which was understood to have a "poor" condition rating and others identified as "fair":



			Construction		tion	Longth	Year in	Condition	Replacement
Asset ID	Asset Name	Asset Class	Material	Location From	Location To	Length (m)	Service	Rating	and/or Upgrade Cost
	Water			Moira Riv Conne					
WS21-67	Main	Distribution	Cast Iron	Bridge Street East	Moira Street	91	1930	Poor	\$ 900,000
	Water			Hungerfo	rd Road				2 2 42 222
WS19-31	Main	Distribution	Cast Iron	Park Avenue	Metcalf Street	291	1925	Fair	\$ 246,992
				James Street North					
WS19-33	Water Main	Distribution	Cast Iron	Jamieson Street East	End (South- East)	112	1925	Fair	\$ 95,200
				James Street South					
WS19-34	Water Main	Distribution	Cast Iron	River Street East	End (North- West)	74	1925	Fair	\$ 62,900
	Water			Jamieson S	Street East				
WS19-35	Main	Distribution	Cast Iron	Mary Street	Colborne Street	95	1925	Fair	\$ 80,750
	Water			Jamieson 9	Street East				0.00.450
WS19-36	Main	Distribution	Cast Iron	Louisa Street	Mary Street	97	1925	Fair	\$ 82,450
				Jamieson 9	Street East				
WS19-37	Water Main	Distribution	Cast Iron	James Street North	Louisa Street	94	1925	Fair	\$ 79,900
				Jamieson S	Street East				
WS19-38	Water Main	Distribution	Cast Iron	Colborne Street	Victoria Street North	97	1925	Fair	\$ 82,450

Priority water supply services assets recommended for further review are summarized in Table 6c of this AMP Report.

#### 6.4 Wastewater Services

Based on the details presented in Table 4d – Detailed Summary of Municipal Assets (Wastewater Services), and reported in the Wastewater Asset Study (Greenview, 2019c), the following priority wastewater services assets are recommended to be investigated further as part of future repairs, reconstruction/rehabilitation, replacement and/or maintenance opportunities. The priority wastewater services assets for further investigation were determined by the following procedure:

1. Sorting the data for all wastewater services assets based on the condition rating, from lowest (poor) to highest (good), followed by sorting on Year in Service (or Last Upgrade Year).

The sorting of wastewater services assets by this methodology resulted in an asset set of Sewer Mains of



generally similar age and construction material:

Asset ID	Asset Name	Asset Class	Construction Material	Loca Location	tion Location	Length (m)	Year in Service	Condition Rating	Replacement and/or Upgrade
				From	То				Cost
				Moira	Street				
WW19-70	Sewer Mains	Distribution	Asbestos Cement	Highway 37	Old Bogart Road	291	1930	Poor	\$ 145,500
			***************************************	Moira	Street				
WW19-71	Sewer Mains	Distribution	Asbestos Cement	Old Bogart Road	Arthur Street	240	1930	Poor	\$ 120,000
				Arthur	Street				
WW19-14	Sewer Mains	Distribution	Asbestos Cement	Brooklyn Road	Louisa Street	263	1931	Poor	\$ 131,500
***************************************				Hannah Street		331100000000000000000000000000000000000			
VVV19-31	Sewer Mains	Distribution	Asbestos Cement	Louisa Street	James Street North	92	1925	Fair	\$ 46,000
				James St	reet North	105			
VVV19-38	Sewer Mains	Distribution	Asbestos Cement	Jamieson Street East	Hannah Street		105 1925 128 1925	Fair	\$ 52,500
				James Str	eet South			***************************************	
VVV19-39	Sewer Mains	Distribution	Asbestos Cement	River Street East	George Street	128		Fair	\$ 64,000
				Jamieson	Street East				
WW19-41	Sewer Mains	Distribution	Asbestos Cement	Colborne Street	Victoria Street North	102	1925	Fair	\$ 51,000
***************************************	Sewer		Asbestos	Jamieson	Jamieson Street East				
WW19-42	Mains	Distribution	Cement	Colborne Street	Mary Street	96	1925	Fair	\$ 48,000
				Jamieson	Street East				
WW19-43	Sewer Mains	Distribution	Asbestos Cement	Louisa Street	James Street North	90	1925	Fair	\$ 45,000
	0-		A a b t	Jamieson Street East					
VW19-44	Sewer Mains	Distribution	Asbestos Cement	Mary Street	Louisa Street	97	1925	Fair	\$ 48,500

In addition to the above noted Sewer Main sections that are recommended for further review, the Municipality has an immediate need to expand the capacity of their existing waste stabilization ponds. The existing two (2) waste stabilization ponds are understood to be in fair condition at this time; however, their volumetric capacity is understood to be insufficient for the volumes of wastewater requiring treatment, resulting in unplanned and



planned wastewater discharges to the adjacent Stoco Lake. A new waste stabilization pond is required to address the deficiency in wastewater flow generated in the Village of Tweed.

Priority wastewater services assets recommended for further review are summarized in Table 6d of this AMP Report.

#### 6.5 Stormwater Assets (New June 2021)

Based on the details presented in Table 4e – Detailed Summary of Municipal Assets (Stormwater Assets), and reported in the Stormwater Asset Study (Greenview, 2021a), the following priority stormwater assets are recommended to be investigated further as part of future repairs, reconstruction/rehabilitation, replacement and/or maintenance opportunities. The priority stormwater assets for further investigation were determined by the following procedure:

1. Sorting the data for all stormwater assets based on the current level of service, whether the catchment area systems were interpreted to be resilient to a 5-year storm, and condition rating, from lowest (poor) to highest (good).

The sorting of stormwater assets by this methodology resulted in an asset set recommended for further review as follows:

Asset ID	Asset Name, Description, Area (ha)	Inlets (#)	Outlets (#)	Number of Properties At Risk of Flooding to 100- year Storm	Systems Resilient to a 5- year Storm	Year in Service	Condition Rating	Level of Service	Replacement and/or Upgrade Cost
STW20- 06	Tweed Centre Catchment Area (Large) 60 ha	172	1	0	No	1983	fair	5	\$ 1,720,000
STW20- 09	Tweed East Catchment Area (Medium) 6 ha	27	1	0	No	1988	fair	4	\$ 270,000
STW20- 12	Tweed North Catchment Area (Multi) 30 ha	61	individual outlets	10	Yes	1983	fair	4	\$ 610,000
STW20- 01	Actinolite Catchment Area (Small) 1 ha	unknown	unknown	10	unknown	unknown	unknown	unknown	unknown



With respect to further review of the above noted stormwater related assets, the following additional review activities are recommended:

- 1. Stormwater catchment areas of Tweed Centre (STW20-06) and Tweed East (STW20-09) are recommended to be reviewed in additional detail, in order to better establish whether there are any undetermined factors that influenced the calculations of whether the two (2) catchment area systems were resilient to a 5-year storm. Based on available information at the time of completion of the Stormwater Asset Study (Greenview, 2021a), the Estimated Inlet Flow rates for both Tweed Centre and Tweed East were larger than the Estimated Outlet Flow rates, resulting in both catchment area systems being identified as not resilient to a 5-year storm. Additional study is recommended to confirm or disprove these preliminary calculations.
- 2. Based on the review of the Tweed North catchment area (STW20-12), the stormwater systems in this catchment area were determined to be complex, with an unknown quantity of outlets identified as a data gap, with assumed discharge to the Moira River. Additional study is recommended in this area to further establish the quantity of outlets and better understand how stormwater is managed in the catchment area.
- 3. At the time of completion of the Stormwater Asset Study, it was understood that there were no known stormwater assets located within the small catchment area associated with the hamlet of Actinolite (STW20-01); however, if any stormwater assets are identified within the hamlet of Actinolite in the future, then additional study is recommended to be completed in the catchment area to establish specific locations of any/all inlet and outlet locations, and related components, and have them integrated into the Municipality's Asset Management Planning documents.

Priority stormwater assets recommended for further review are summarized in Table 6e of this AMP Report.

#### 6.6 Coordination of Asset Replacements/Upgrades (Updated June 2021)

Given the interconnection of surficial linear assets (i.e. roads, bridges and large culverts) and sub-surface linear assets (i.e. water mains, sewer mains, stormwater assets, etc.), the Municipality should consider combining asset replacements/upgrades where the upgrade/replacement of one (1) asset may impact other asset categories in the same area (i.e. if a water main requires replacement, also consider replacement of the sewer mains, stormwater assets, and road pavement surface in the same area). Similarly, the Municipality may consider extending a replacement schedule for a given asset in order to time its replacement with a planned replacement schedule for another related asset.

Financial benefits (i.e. cost savings) may be attained with this asset management approach.

#### 6.7 Recommendations for Future Asset Management Planning Activities (Updated June 2021)

It is recommended that, as part of any future development of this AMP Report, the Municipality should consider completing a detailed operational review of all assets, with a focus on the potential for decreasing the quantity of existing Municipal assets (i.e. buildings, vehicles, etc.) while at the same time maintaining the current level of service expected by its ratepayers. Inclusion of all Municipal asset categories in a future AMP is required by no later than July 1, 2023, per Section 5 (1) of O.Reg. 588/17 (Appendix A).

Updates to studies related to Municipality assets should be completed in accordance with timelines outlined in O.Reg. 588/17 (as applicable).

As noted in Section 5.5, it is recommended that the Municipality consider conducting a detailed risk analysis for municipal assets as part of future asset management planning activities to further assist in the decision-making process of establishing priority assets for additional review, upgrade and/or replacement.



#### 7.0 Closing

Greenview has prepared this Asset Management Plan Report (Version 1.2) in order to meet with the requirements of O.Reg. 588/17 – Asset Management Planning for Municipal Infrastructure, including the following core asset categories:

- 1. Roads.
- 2. Bridges and Large Culverts.
- 3. Water Supply Services (Updated August 2021).
- 4. Wastewater Services.
- 5. Stormwater Assets (New June 2021)

This report is governed by the attached statement of service conditions and limitations (Appendix B).

All respectfully submitted by,

**Greenview Environmental Management Limited** 

Dan Hagan, P.Geo.

Senior Project Manager / Geologist

Tyler H. Peters, P.Eng.

**Project Director** 



#### 8.0 Selected References

Greenview, 2019a. 2019 Road Needs Study. Greenview Environmental Management Limited, August 30, 2019.

Greenview, 2019b. Water Asset Study – Municipal Water System. Greenview Environmental Management Limited, August 30, 2019.

Greenview, 2019c. Wastewater Asset Study – Municipal Wastewater System. Greenview Environmental Management Limited, August 30, 2019.

Greenview, 2019d. 2019 Asset Management Plan Report (Version 1.0). Greenview Environmental Management Limited. December 06, 2019.

Greenview, 2021a. Stormwater Asset Study. Greenview Environmental Management Limited, June 2021.

Greenview, 2021b. Asset Management Plan Report (Version 1.1). Greenview Environmental Management Limited, June 28, 2021.

Jewell Engineering Inc., 2019. Municipality of Tweed – 2018 OSIM Bridge Inspection Report. Jewell Engineering Inc., January 24, 2019.

Ontario Ministry of Transportation (MTO), 2016. Manual for Condition Rating of Flexible Pavements – Distress Manifestations (SP-024). MTO Highway Standards Branch, 2016.

Ontario Ministry of Transportation (MTO), 1989. Manual for Condition Rating of Surface-Treated Pavements – Distress Manifestations (SP-021). MTO Research and Development Branch, August 1989.

Ontario Ministry of Transportation (MTO), 1989. Manual for Condition Rating of Gravel Surface Roads (SP-025). MTO Research and Development Branch, August 1989.

Ontario Regulation 232/02 - Minimum Maintenance Standards for Municipal Highways.

Ontario Regulation 588/17 - Asset Management Planning for Municipal Infrastructure.

Queen's Printer for Ontario, 2012. Building Together – Guide for Municipal Asset Management Plans, Infrastructure Ontario. 2012.

Quinte Conservation Authority Flood Mapping, 2009 & 1983.

Statistics Canada, 2019. Census Profile, 2016 Census, Municipality of Tweed. https://www12.statcan.gc.ca/census-recensement/2016/dp-

pd/prof/details/page.cfm?Lang=E&Geo1=CSD&Code1=3512030&Geo2=PR&Code2=01&SearchText=Tweed&SearchType=Begins&SearchPR=01&B1=All&GeoLevel=PR&GeoCode=3512030&TABID=1&type=0



	Year Acquired/	Expected												
		Replacement/	Historical											
Asset	Updated	Renovation	Cost	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
Arena	2010	2030	1,255,899.85	127,000.00	105,000.00	65,000.00	20,000.00					2,000,000.00	140,000.00	
Arena Hot Water Tank	2013	2023	1,765.54		1,765.54									4770 004 45
Arena Lights	2017	2032	176,684.45											176,684.45
Arena Dehumidifers	2014	2022	31,545.60	45,000.00						50,000.00		5 000 00		
Zamboni (includes refurb and ice	2006	2024	160,694.33			185,000.00			5,000.00			5,000.00		
Arena cooling tower	2015	2025	15,912.00				15,912.00							35,000.00
Arena compressor	2017	2032	28,317.30											35,000.00
Cameras - parking lot		2022		3,000.00										
Canteen - Grill		2022		1,500.00										
Scrolling Message Board		2022		1,650.00										
Control Box for Score clock		2022		6,000.00					6 000 00					
Ice edger		2022		6,000.00					6,000.00					
Floor scrubber	2010	2022	4 070 00	4,000.00	7.500.00									
Maribank Ball Diamond Fencing	2013	2023	4,273.92		7,500.00				48,536.42					
Ball Diamond Upgrades Stoco Ball Diamond Netting	2017	2027 2029	48,536.42 9,259.60						40,330.42		9,259.60			
Ball Diamond Netting	2019 2018	2029	9,259.60 17,641.26							17,641,26	5,255.00			•
LED lighting Stoco/Charelton	2018	2018	45,000.00	45,000.00						17,041.20				
Charlton In-Field screenings and		2022	45,000.00	10,000.00										
Pumptrack/Skatepark		2022		250,000.00										
New Recreation Area Shelter		2022		40,000.00										
Fencing		2022		5,000.00										
Tree Removal and Replanting		Annuai		15,000.00	6,000.00	6.000.00	6.000.00	6.000.00	6.000.00	6,000,00	6,000.00	6,000.00		
Garbage and Recylcing		2022		5,000.00	0,000.00	0,000.00	0,000.00	0,000.00	0,000.00		-•			
Beach sand		2022		25,000.00										
Aqua Thruster (2)		2022	•	20,000.00										
Tweed Open Shelter	1992	2032	30,000.00	20,000.00										30,000.00
Park Washroom	1987	2027	34,637,40						34,637.40					
Marlbank Pavillion	2020	2060	94,000.00											
Stoco Pavillion	2016	2031	41,454.06										41,454.06	
Tweed Storage	2012	2032	5,689,42											5,689.42
Barns		2022	•	2,500.00										
Tweed Playground Equip	2021	2041	314,574.19											
Maribank Playground Equip	2017	2037	13,006.28											
Outdoor fitness equipment	2018	2033	50,000.00											
Fountain	2021	2028	10,542.34							10,542.34				
Mower - 13 Kubota	2013	2023	11,571.23		15,000.00									
Benches	2019	2039	4,948.11											
Picnic tables	2019	2039	3,250.72											
Vacuum sweeper	2019	2039	2,784.97											
Riding mower - 15	2015	2025	10,583.04				15,000.00					15,000.00		
Riding mower - Kubota	2020	2030	14,135.00									15,000.00		
Mower		2022		15,000.00	70 000 00									
Truck with Dump Box		2023	F 000 00		70,000.00									
Grass catcher	2016	2036	5,088.00	4 000 00										
Rake for tractor		2022	3E 000 00	1,000.00										
Royal Victoria Parkette Gazebo		2022 2022	25,000.00	40,000.00 1,000.00										
Planters 2009 GMC Pickup	0000	2022 2024		1,000,00		35,000.00								
	2009	2024	35,000.00			35,000.00								
2018 Dodge Truck Decorations	2018		32,555.08	10,000.00	5,000.00	5,000.00	5.000.00	5,000.00	5,000.00	5,000.00	5,000.00	5,000.00		
Boat Launch		Annual	154 225 02	10,000.00	5,000.00	5,000.00	3,000.00	3,000.00	5,500.00	5,500.00	0,000.00	5,555.50		
Boat Launch Parking	2018 2018	2048 2028	154,326.03 14,587.30							14,587.30				
Pool	2010	2020		200.000.00		<u> </u>				,				
Pool pumps	2010	2022	8,000.00	200,000.00						8,000.00				
1 oo pumps		2020	0,000.00							-,				

Asset	Year Acquired/ Last Updated	Expected Replacement/ Renovation	Historical Cost	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
Gas heater to pool	Opuatou	2022	0031	25,000.00	2020	2024	2020	2020						
Splash Pad	2015		456,963,02	23,500.00	1,500.00		2,000.00	1,000.00	4,500.00	2,000.00				
Kiwanis Pavillion	2013		96,788,64	25,500.00	1,300.00		2,000.00	1,000.00	4,500.00	2,000.00				
Queensborough Hall	2011	2022	45.062.21	357,000.00										
Actinolite Hall	2011	2051	21.270.26	00.000,100										
Actinolite Furnace	2019		6,410.88											
Thomasburg Hall	2012		18,426,98											
Thomasburg Furnace	2019		3.943.20											
Jailhouse Signage	2013		2,947.52	-				-		-				
Jailhouse Building	1898		7,880.40											
Hydrant Painting		Annual	.,	4.000.00	4,000.00	4,000.00	4,000.00	4,000.00	4,000.00	4,000.00	4,000.00	4,000.00		
Banners		2022		6,000,00	.,	.,		•••	•	·				
Tweed Welcome Signs	2019		8,242.24	-,										
Total Costs Other grants Parks and recreation reserve to Parkland reserve fund to use Splash pad reserve to use Pool reserve to use Heritage reserve to use Arena reserve to use			3,573,038.81	1,294,150.00 541,400.00 77,340.50 43,154.19 1,250.00 89,000.00	215,765.54	300,000.00	67,912.00 - 67,912.00	16,000.00	113,673.82	117,770.90	24,259.60	2,035,000.00	181,454.06	247,373.87 247,373.87
Remaining Amounts to be Funded				438,382.31	215,765.54	300,000.00	67,912.00	16,000.00	113,673.02	117,770.90	·			
2022 Transfer to Reserves Requirement 5 year basis only - arena 5 year basis only - parks 5 year basis only - splashpad 5 year basis only - pool 5 year basis only - community development/heritage			147,527.44 91,478.97 2,200.00 - 5,800.00	-	107,882.77	100,000.00	16,978.00	3,200.00	18,945.64	16,824.41	3,032.45	226,111.11	18,145.41	22,488.53

Asset	2033	2035	2036	2037	2039	2040	2041	2048	2051	2052	2054	2060
Arena												
Arena Hot Water Tank												
Arena Lights												
Arena Dehumidifers												
Zamboni (includes refurb and ice												
Arena cooling tower												
Arena compressor												
Cameras - parking lot												
Canteen - Grill												
Scrolling Message Board	•											
Control Box for Score clock												
Ice edger												
Floor scrubber												
Marlbank Ball Diamond Fencing		<del></del> -										
Ball Diamond Upgrades											•	
Stoco Ball Diamond Netting												
Ball Diamond Netting												
LED lighting Stoco/Charelton												
Charlton In-Field screenings and												
Pumptrack/Skatepark												
New Recreation Area Shelter												
Fencing												
Tree Removal and Replanting												
Garbage and Recylcing												
Beach sand												
Aqua Thruster (2)												
Tweed Open Shelter												
Park Washroom												
Marlbank Pavillion												94,000.00
Stoco Pavillion												34,000.00
Tweed Storage												
Barns												
Tweed Playground Equip							314,574.19					
Maribank Playground Equip				42 000 20			314,374.19					
Outdoor fitness equipment	E0 000 00			13,006.28								
Fountain	50,000.00											
Mower - 13 Kubota												
Benches					4 040 44	2 500 00	2 500 00					
Picnic tables					4,948.11 3,250.72	2,500.00	2,500.00					
Vacuum sweeper												
Riding mower - 15					2,784.97							
Riding mower - Kubota												
Mower												
Truck with Dump Box												
Grass catcher			5,088.00									
Rake for tractor			5,000.00									
Royal Victoria Parkette Gazebo												
Planters												
2009 GMC Pickup												
2018 Dodge Truck	32,555.08											
Decorations	02,000.00											
Boat Launch								175,000.00				
Boat Launch Parking								., 0,000.00				
Pool												
Pool pumps												
Anatoridam												

Asset	2033	2035	2036	2037	2039	2040	2041	2048	2051	2052	2054	2060
Gas heater to pool												
Splash Pad		456,963.02										
Kiwanis Pavillion				-							96,788.64	
Queensborough Hall									45,062.21			
Actinolite Hall									21,270.26			
Actinolite Furnace					6,410.88							
Thomasburg Hall										18,426.98		
Thomasburg Furnace					3,943.20						<del></del>	
Jailhouse Signage	2,947.52											
Jailhouse Building						7,880.40						
Hydrant Painting												
Banners												
Tweed Welcome Signs					8,242.24							
Total Costs	05 500 60	450,000,00	E 000 00	40.000.00	00 500 40	40 000 40	247.074.40	175,000.00	66,332.47	18,426.98	96,788.64	94,000.00
Other grants	85,502.60	456,963.02	5,088.00	13,006.28	29,580.12	10,380.40	317,074.19	175,000.00	00,332.47	10,420.50	30,700.04	54,000.00
Parks and recreation reserve to												
Parkland reserve fund to use												
Splash pad reserve to use												
Pool reserve to use												
Heritage reserve to use	2.947.52					7.880.40						
Arena reserve to use	2,047.02					7,000.40						
Remaining Amounts to be	82,555.08	456,963.02	5,088.00	13,006.28	29,580.12	2,500.00	317,074.19	175,000.00	66,332.47	18,426.98	96,788.64	94,000.00
2022 Transfer to Reserves	6,879.59	32,640.22	339.20	812.89	1,643.34	131.58	15,853.71	6,481.48	2,211.08	594.42	2,932.99	2,410.26
5 year basis only - arena	0,079.39	32,040.22	338.20	612.05	1,043.34	131.36	13,633.71	0,401.40	2,211.00	337.72	2,502.05	2,410.20
5 year basis only - parks												
5 year basis only - parks												
5 year basis only - splastipad 5 year basis only - pool												
5 year basis only - community												
development/heritage												
an are principalities												

#### Municipality of Tweed 2022 Capital Budget Planned Financing Sources

Account	Capital Project	2022 Budgeted Expense	Federal Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-510-58000	Recreation Area Shelter	40,000.00				40,000.00				-	
01-510-58000	Repainting barns	2,500.00								2,500.00	
01-510-58000	Royal Victoria Parkette Gazebo	40,000.00				37,340.50				2,659.50 15,000.00	
01-510-58018 01-510-58019	Tree removal and replanting Garbage and recycling receptacles	15,000.00 5,000.00								5,000.00	
	PARKS Planters	1,000.00								1,000.00	
01-510-58039	Christmas/Seasonal Decorations	10,000.00				5,000.00				5,000.00	
01-510-58050	LED lighting at Stoco/Charelton	45,000.00				•				45,000.00	
01-510-58050										10,000.00	
01-510-58050		250,000.00			200,000.00			43,154.19		6,845.81	
01-510-58050		5,000.00								5,000.00 25,000.00	
01-510-58050 01-510-58132	Beach sand New mower	25,000.00 15,000.00								25,000.00 15,000.00	
01-510-58132		1,000.00								1,000.00	
	Aqua thruster (2)	20,000.00								20,000.00	
_	,,	484,500.00		-	200,000.00	82,340.50	-	43,154.19	-	159,005.31	_
							-				
01-512-58014	HAMLET REC Actinolite Hall Improve									3,000.00	
01-514-58014	HAMLET REC Marlbank Pavilion Impi									3,000.00 3,000.00	
01-516-58014 01-516-58020	HAMLET REC Queensborough Hall In Queensborough Hall Renovations	3,000.00 357,000.00			256,400.00					100,600.00	
	HAMLET REC Thomasburg Hall Impre				230,400.00					3,000.00	
01-310-30014	TIAMEET NEO THOMASOURY HAIR IMPO	369,000.00		-	256,400.00	-		•		112,600.00	
											-
01-520-58000	Arena - upstairs renovations	25,000.00				25,000.00				-	
01-520-58000	Arena - accessible lift/washroom	102,000.00			85,000.00	17,000.00				-	
01-520-58132		45,000.00				45,000.00				-	
01-520-58132		6,000.00				6,000.00					
01-520-58132	Cameras - parking lot	3,000.00				623.00				2,377.00 1,500.00	
01-520-58132 01-520-58132	•	1,500.00 1,650.00								1,650.00	
01-520-58132		6,000.00				6,000,00				1,000.00	
01-520-58132		4,000.00				4,000.00					_
		194,150.00	-	- <u>-</u>	85,000.00	103,623.00	•	-		5,527.00	_
01-525-58000	Splashpad filter pump replacement	3,000.00								3,000.00	
01-525-58000	Splashpad rain diverter	20,000.00		•		1,250.00				18,750.00 500.00	
01-525-58000	Splashpad replace painting instead of	500.00 23,500.00				1,250,00			<del></del>	22,250.00	
		23,300.00	<u> </u>		<u> </u>	1,2,0,00				22,200.00	_
01-555-58000	Pool liner	200,000.00				89,000.00				111,000.00	1
01-555-58052		25,000.00								25,000.00	
	•	225,000.00	-	•	-	89,000.00			-	136,000.00	<u>_</u>

# Municipality of Tweed 2022 Capital Budget Planned Financing Sources

Account	Capital Project	2022 Budgeted Expense	Federal . Funding	Provincial Funding	Other Grant Funding	Reserve Funding	Reserve Funds Funding	Obligatory Reserve Fund Funding	Other Funding Sources	Municipal Tax Impact	Notes
01-125-58017	Hydrant Painting	4.000.00								4,000.00	
01-125-58132	,	6,000.00				_				6,000.00	_
		10,000.00	-	-			<u> </u>			10,000.00	=



# Queensborough Community Centre Structural Assessment



Prepared for:

The Municipality of Tweed

255 Metcalf St. Postal Bag 729 Tweed, Ontario KoK 3Jo

Submitted by

Q&E Engineering Inc. 684 Moneymore Road, Roslin, Ontario KoK 2Yo

T: (613) 707-0706 F: (613) 777-4925 www.qe-engineering.com

Ta	ible o	of Contents	
1.	BAG	CKGROUND AND INTRODUCTION	1
2.	OB	SERVATIONS	1
	2.2 2.3 2.4	Original Building Floor	Ţ
3.	REC	COMMENDATIONS AND CONCLUSIONS	2
		Table of Appendices	

APPENDIX A – Approximate Building Sketches APPENDIX B – Photographs

#### 1. BACKGROUND AND INTRODUCTION

The week of July 26, 2021, the Municipality of Tweed was notified that the Queensborough Community Centre had several noted deficiencies. On August 4, 2021 a local Contractor assessed the structure and recommended that the kitchen addition be replaced. On August 5, 2021, Greenview Environmental completed a preliminary assessment of the structure as part of their asset management review. Their report recommended closure of the structure until a structural Engineer could assess the condition of the building. At the August 24, 2021 Council Meeting, the Municipality resolved to close the structure until the repairs are completed.

At the request of Ms. Gloria Raybone, CAO/Treasurer, Q&E Engineering Inc. completed a structural assessment of the Community Centre on September 15, 2021.

The existing Community Centre is a single-story brick masonry building founded on stone rubble foundation. The floor and roof are of wood construction. The year of construction was noted as 1901. It is understood that the original building was occupied as a schoolhouse and was later converted to a community hall (assembly occupancy). A contemporary timber framed structure on masonry (block) foundation was added to the west side of the original structure circa 2010. It is understood that the addition was designed and constructed by local volunteers. The building has been closed since early 2020 at the start of the Covid-19 pandemic. It is understood that the Municipality has not utilized the HVAC system in this building since its closure.

The original building, measuring approximately 40 feet x 56 feet, is comprised of a large event space and two small bathrooms and a utility/storage space at the front of the building (north side). The addition, measuring approximately 16 feet x 20 feet, has been used as a kitchen space for events. An approximate layout of the building has been included for reference in Appendix A. Select photographs of the building have been included in Appendix B.

The scope of work for this assessment included visual inspection of the exposed/accessible areas of the structure, removal of localized floor structure for visual access to the subfloor space, structural analysis/evaluation of select structural components, and a report summarizing findings and recommendations for corrective action and associated costs to help the Municipality effectively plan for future use of the building.

#### 2. Observations

#### 2.1 Original Building Floor

The original building floor consists of timber floorboards and 2x10 rough sawn floor joists spaced at 16 inches on center. Localized sagging of the floor was noted near the north (front) exterior wall. A small hole was cut in the washroom floor to allow for visual inspection. The crawl space floor in this area was covered in batt insulation that was moist at the time of inspection. The presence of the batt insulation has likely been contributing to moisture accumulation in this area. The extent of the batt insulation could not be confirmed. It appeared that the joists were supported by wood blocking at approximate mid span of the joists. The blocking appeared loose which suggests some of the blocking may have rotted and is no longer providing support to the joists. In addition, the joists appeared moist and localized areas of severe rot was observed. Given the exposure condition in this area and the observed floor sag, it is speculated that the joists near the front of the building are likely in poor condition.

Floorboards had been previously removed in a section of flooring on the south side of the building which allowed for review of the floor joists and the crawlspace in this section. There were no signs of insulation in this portion of the floor and the area in general appeared to be relatively dry compared to the area near the front of the building described above. The floor joists in this area had been replaced, presumably in conjunction with the

18.10

floorboard replacement. The newer joists are nail laminated 2 ply 2x10 SPF dimension lumber, which generally appeared to be in good condition.

#### 2.2 Original Building Roof

The original building roof trusses appeared to be in good condition. The bell tower was not accessible for inspection, however, there were no obvious signs of structural distress when viewed from the exterior. The overhang soffit and overhang outriggers on the south side of the building were significantly deteriorated. Localized deterioration was also noted in the fascia boards along the other sides of the original building. It is speculated that some of the roof truss top chord overhangs may have sustained deterioration behind the areas of fascia board deterioration. This will need to be further investigated during future rehabilitation work.

#### 2.3 Original Building Exterior

The original building exterior is comprised of a stacked stone rubble foundation and masonry brick walls. The adjacent land does not provide positive drainage away from the building. A garden box located along the south side of the building appeared to be an area where water tends to pool. The grade at the southwest corner of the building is currently above the top of the foundation.

Localized cracking and mortar loss was noted in several locations in the brick and stone foundation. The most prominent deterioration (mortar loss) was found in the northeast corner of the foundation within the crawl space of the kitchen addition.

#### 2.4 Kitchen Addition

The addition consists of conventional wood framed walls, pre-engineered wood roof trusses, and a wood floor support on 8-inch block wall foundation walls founded on poured concrete strip footings. The wall and roof structure generally appeared to be in good condition.

A hole was cut in the floor to gain access into the crawl space to facilitate inspection of the floor and foundation. The footing was found to have insufficient ground cover to provide frost protection. Minimum ground cover for this area is 5 feet, the current ground for the existing footings were found to vary from 2.5 to 3.5 feet. The crawl space was not fully backfilled and the clear height to underside of the floor joists was approximately 3 feet. An existing downspout was noted to have been discharging rainwater at the northwest corner of the addition. The combined effect of poor drainage, lack of backfill, and insufficient ground cover has caused significant cracking throughout and an inward bulge of approximately 1 inch in the west block wall.

The crawl space was moist at the time of inspection, and it is assumed to be consistent due to limited ventilation. This exposure condition has caused widespread rot along the bottom of the existing 2x10 floor joists, reducing their strength.

#### 3. Recommendations and Conclusions

Based on our review and findings the following repair recommendations should be completed prior to reopening of the Community Centre:

- Remove wet batt insulation in the crawl space of the original building to help reduce moisture accumulation
- Install mechanical ventilation to help keep the crawl space of the original building dry.
- Repair original floor structure and replace floorboards
- Replace deteriorated outrigger, soffit boards, and fascia board.
- Install drip edge to roof structure.

- Repair original stone foundation and brick by repointing with lime-based mortar.
- Remove the existing garden at the rear of the building and regrade as required.
- Install subdrain around perimeter of foundation and allow for future hookup to municipal services.
- Demolish addition and reconstruct with proper footings and foundation walls

Given the size of the addition, and the type of deficiencies noted, it would not be cost effective to repair. As community centres are required by the Ontario Building Code (OBC) to be designed for assembly occupancy loading, the Community Centre does not fall under Part 9 of the OBC and the repair work and reconstruction of the addition will need to be designed and stamped by a Professional Engineer.

Table 1 summarizes the budgetary cost estimates to complete the above recommended repairs:

Repair Recommendations	Construction Cost Estimate
1. Repair original floor structure and replace	\$85,000
floorboards	
2. Replace all fascia boards, install drip edge,	\$15,000
and repair west roof overhang	
Repair bricks and stone foundation	\$20,000
Replace addition	\$100,000

Table 1. Summary of budgetary construction cost estimates

The Municipality should also consider completing a hazardous building material survey to facilitate the work. In addition to the above estimates, an additional budget of 12% should be allocated for engineering and inspection services.


Respectfully Submitted,

Q&E Engineering Inc.

Quan Tan, P.Eng.

Consulting Engineer/Office Manager

# Appendix A Approximate Building Sketches



# Appendix B Photos



Photo 1. Building north elevation (front)



Photo 2. Building west elevation





Photo 3. Building south elevation (rear)



Photo 4. Building east elevation






Photo 5. Addition north elevation (front)




Photo 6a. Localized cracking in NW foundation

6b. Localized cracking in SW foundation





Photo 7. Damaged soffit in addition




Photo 8. Mortar loss in exterior stacked stone foundation





Photo 9. Grading above foundation line



Photo 10. Water pooling and mortar loss at SE building corner





Photo 11. Localized step cracking in brick wall (several locations have been previously repaired)




Photo 12. Interior facing south





Photo 13. Removed floorboards on south side of building




Photo 14. Storage Space




Photo 15. NE bathroom



Photo 16. One location of heaved floorboards





Photo 17. Lower attic space of original building looking west



Photo 18. Upper attic space of original building in good condition





Photo 19. Crawlspace on south side of original building



Photo 20. Damp batt insulation found in crawlspace under NW bathroom






Photo 21. Photo illustrating depth of sagging in north hallway



Photo 22. Crawlspace under addition looking west





Photo 23. Crawlspace under addition showing connection to original structure



Photo 24. Crawlspace under addition showing condition of floor joists






Photo 25. Wide crack in addition foundation wall




Photo 26. Photo illustrating 2" shift in addition foundation wall





Photo 27. Photo illustrating extent of rot in addition floor joists